

ANNUAL SURVEYS.

No. 26851 Survey held at Liverpool Date Jan 6th 1880.
 on the Ship "Star of Greece" Master Legg
 Tonnage 1227 Built at Belfast When built 1868 - 9 mo
 By whom built Harland Owners J. Corry & Co
 Port belonging to Belfast Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Princes Dry Dock.

Last Survey, No. 22336 Port of Iron Classed AI 12.78
S.S. Lon No 2-76

The present Condition of the	Good	Treenails	Rivets.	Good	Windlass and Capstan	Good
Decks						
Waterways	4	Breasthooks and Stemson		4	Pumps	4
Comings	4	Transoms, Pointers, and Crutches		4	Boats	4
Upper Deck Beams & Fastenings	4	Timbers of the Frame		4	Masts, Yards, &c.	4
Lower Deck Beams & Fastenings	4	Keelsons		4	Sails	4
Planksheers	4	Clamps and Shelves		4	Anchors No. of <u>3B - 1S - 2K</u>	
Sheerstrakes	4	Ceiling		4	Cables <u>pt seen</u>	Good
Topsides	4	Rudder		4	Hawsers and Warps	and
Wales	4	Copper Cement When put on <u>68</u>			Standing & Running Rigging	Sufficient
Plank (Bottom) and Counter	4					

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good

Bottom sighted cleaned and coated with paint and the vessel being now in a good & efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool Feb 6th 1880

Character assigned

* AI.

T. Shilston

Certificate (if required)

No. ✓ Survey held at Liverpool Date Jan 31st 1880.
 on the Ship "Iron Queen" Master W. Smith
 Tonnage 786 Built at Liverpool When built 1863 - 10 mo
 By whom built Potter Owners G. N. Fletcher & Co
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Queens Dry Dock.

Last Survey, No. 19614 Port of Iron Classed AI 8.77
S.S. Lon No 3-77

The present Condition of the	Good	Treenails	Rivets.	Good	Windlass and Capstan	Good
Decks						
Waterways	4	Breasthooks and Stemson		4	Pumps	4
Comings	4	Transoms, Pointers, and Crutches		4	Boats	4
Upper Deck Beams & Fastenings	4	Timbers of the Frame		4	Masts, Yards, &c.	4
Lower Deck Beams & Fastenings	4	Keelsons		4	Sails	4
Planksheers	4	Clamps and Shelves		4	Anchors No. of <u>3B - 1S - 2K</u>	
Sheerstrakes	4	Ceiling		4	Cables <u>pt seen</u>	Good
Topsides	4	Rudder		4	Hawsers and Warps	and
Wales	4	Copper Cement When put on <u>63</u>			Standing & Running Rigging	Sufficient
Plank (Bottom) and Counter	4					

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good.

Bottom sighted cleaned and coated with paint, and the vessel being now in a good and efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool Feb 6th 1880

Character assigned

* AI.

T. Shilston

Certificate (if required).

Star of Greece
Iron Queen
26851



© 2019

Lloyd's Register
Foundation