

# ANNUAL SURVEYS.

26065

No. 38,901. Survey held at London Date, first Survey Feb 7 Last Survey Feb 14 18 80

No. in on the SS Newburn Master Coleman

Reg. Book. 199 Tonnage 443 Built at Sunderland When built 1861-3 mo.

By whom built Sainy Owners J. Ferniwick Wm

Port belonging to London Destined Voyage Coasting

If Surveyed Afloat or in Dry Dock Porton Victoria dock

Last Survey, No. 24454 Port of Iron

Classed Ⓐ Years assigned 10.78 Character in Register Book SS Lin M3-78

Present Condition of the Decks <u>good</u>	Treenails <u>Rivets some unusd good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>in bottom</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Condition, how ascertained <u>Seen SK</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>good</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors, No. of <u>3 Bcs. SK &amp; Redys</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>Part on SK</u>
Wales <u>"</u>	Rudder <u>Repaired</u>	Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Good</u> When put on <u>now</u>	Standing and Running Rigging <u>"</u>
Engine Room Skylights <u>good</u>	Caulking of Bottom, Deck, & Waterways <u>good</u>	Cargo and Main Hatchways <u>good</u>
Coal Bunker, Openings, Lids, &c. <u>good</u>	Scuppers <u>good</u>	Hatches <u>"</u>
General Observations, Opinion as to Class, &c. <u>Bottom &amp;c. contd.</u>		

*She is now in good condition and eligible to remain as classed.*

Committee's Minute Friday, February, 20th 1880

Character assigned Ⓐ Note the limit of 12 Months Certificate (if required) Senhouse Martindale Surveyor to Lloyd's Register of British and Foreign Shipping. Paid 18

1KON491-0229