

ANNUAL SURVEYS.

25848
26067
Dec. 12/3/80
Nov. 11. 1879

No. 126 Survey held at Melbourne Date, first Survey Nov. 9th Last Survey Nov. 11th 1879
Reg. Book. on the Ship "Winefred" Master Alfred Wymark
443 Tonnage 1359 Built at Chester When built 1855
By whom built Sharples & Jones, Sandy Cliff Owners Henry Sharples & others
Port belonging to London Destined Voyage London
If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 19564 Port of Iron
Present Condition of the
Decks Good
Waterways Good
Comings Good
Upper Deck Beams & Fastenings Good
Lower Deck Beams & Fastenings Good
Plating Good
Sheerstrakes Good
Topsides Good
Wales Good
Plating (Bottom) and Counter Good
Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
Treenails Rivets Good
Breasthooks and Stemson Good
Transoms, Pointers, and Crutches Good
Timbers of the Frame at the Openings Good
Ditto ditto at other places Good
Keelsons Good
Clamps and Shelves Good
Ceiling Good
Rudder Good
Copper or Y.M. Paint When put on Now
Caulking of Bottom, Deck, & Waterways Good
Windlass and Capstan Good
Pumps Good
Boats 4 Good
Masts, Yards, &c. Good
Condition, how ascertained By inspection & enquiry
Sails Double Suit - Good
Anchors, No. of 3 Bow & Stream 2 Kedges
Cables Full length - Good
Hawsers and Warps 10 full length others sufficient
Standing and Running Rigging Good

Observations, Opinion as to Class, &c.
This vessel was partly loaded when surveyed. but outside and so far as could be seen inside she appeared to be in excellent order and condition. She was red down and painted with three coats paint - one of which was Boothwick's Gouling Composition. I consider her well entitled to remain as at present classed and ordered that this survey be noted in the Register

Committee's Minute 23/3/80
Character assigned Tuesday, March, 16th 1880
Douglas. Elder
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18

No. Survey held at Date, first Survey Last Survey 18
No. in Reg. Book. on the Master
Tonnage Built at When built
By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
Present Condition of the
Waterways
Comings
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Planksheers
Sheerstrakes
Topsides
Wales
Plank (Bottom) and Counter
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
Treenails
Breasthooks and Stemson
Transoms, Pointers, and Crutches
Timbers of the Frame at the Openings
Ditto ditto at other places
Keelsons
Clamps and Shelves
Ceiling
Rudder
Copper or Y.M. When put on
Caulking of Bottom, Deck, & Waterways
Windlass and Capstan
Pumps
Boats
Masts, Yards, &c.
Condition, how ascertained
Sails
Anchors, No. of
Cables
Hawsers and Warps
Standing and Running Rigging

General Observations, Opinion as to Class, &c.
Committee's Minute 18
Character assigned
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18