

ANNUAL SURVEYS. 26085

(Received at London Office, 76. 3. 80.)

No. 28984 Survey held at London Date, first Survey 9th March Last Survey 9th March 1880
 No. in on the S.S. "Dublin Castle" Master J. D. Jeffries
 Reg. Book. 464 Tonnage 1856 2nd 2823 Built at Glasgow When built 1877 5th mo
 By whom built Napier Owners D. Currie & Co.
 Port belonging to London Destined Voyage Cape Town
 If Surveyed Afloat or in Dry Dock West India Graving Dock

Last Survey, No. 25207 Port of Gron Classed 100 A1
Years assigned. 12.79
Character in Register Book.

Present Condition of the	Good	Treenails	Rivets	Good	
Decks					
Waterways	<u>do</u>	Breasthooks and Stemson		<u>do</u>	Windlass and Capstan <u>Good</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches		<u>do</u>	Pumps <u>do</u>
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings		<u>do</u>	Boats <u>8 in number</u> <u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places		<u>do</u>	Masts, Yards, &c. <u>do</u>
Planksheers	<u>do</u>	Keelsons		<u>do</u>	Condition, how ascertained <u>from deck enquiry</u>
Sheerstrakes	<u>do</u>	Clamps and Shelves		<u>do</u>	Sails <u>do</u>
Topsides	<u>do</u>	Ceiling		<u>do</u>	Anchors, No. of <u>3 B. 1 St. 2 H.</u> <u>do</u>
Wales	<u>do</u>	Rudder		<u>do</u>	Cables <u>part seen</u> <u>do</u>
Plank (Bottom) and Counter	<u>do</u>	Copper or Y.M. <u>Paint</u> When put on <u>now</u>		<u>do</u>	Hawsers and Warps <u>do</u>
Engine Room Skylights	<u>good</u>	Caulking of Bottom, Deck, & Waterways	<u>good</u>	<u>do</u>	Standing and Running Rigging <u>do</u>
General Observations, Opinion as to Class, &c.		Coal Bunker, Openings, Lids, &c. <u>good</u>	Scuppers <u>do</u>	Cargo and Main Hatchways <u>good</u>	Hatches <u>do</u>

Bottom cleaned & repainted.

This vessel is in good condition & eligible in my opinion to remain as classed.

Committee's Minute Friday, March, 19 1880 W. Paulsen.
Surveyor to Lloyd's Register of British and Foreign Shipping.
 Character assigned 100 A1 Certificate (if required) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in on the _____ Master _____
 Reg. Book. _____ Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
Years assigned. _____
Character in Register Book.

Present Condition of the			
Decks	Treenails		
Waterways	Breasthooks and Stemson		Windlass and Capstan
Comings	Transoms, Pointers, and Crutches		Pumps
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings		Boats
Lower Deck Beams & Fastenings	Ditto ditto at other places		Masts, Yards, &c.
Planksheers	Keelsons		Condition, how ascertained
Sheerstrakes	Clamps and Shelves		Sails
Topsides	Ceiling		Anchors, No. of
Wales	Rudder		Cables
Plank (Bottom) and Counter	Copper or Y.M. When put on		Hawsers and Warps
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways		Standing and Running Rigging
General Observations, Opinion as to Class, &c.	Coal Bunkers, Openings, Lids, &c.	Scuppers	Cargo and Main Hatchways
			Hatches

Committee's Minute _____ 18____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18

