

ANNUAL SURVEYS. 26124

No. 4847 Survey held at Wm. Holland Date, first Survey 24 Aug Last Survey 24 Aug 1880
 No. in on the Boa Sen P. Valhalla Master Peteren
 Reg. Book. 998 Tonnage 998 Built at W. H. Atthpool When built 1874 10 mo
 By whom built W. H. Atthpool Owners J. H. Gresham
 Port belonging to W. H. Atthpool Destined Voyage Landiff to load
 If Surveyed Afloat or in Dry Dock In Ship way

Last Survey, No. 23665 Port of Wm
 Present Condition of the Decks Good Right When seen Good
 Waterways d Breasthooks and Stemson d
 Comings d Transoms, Pointers, and Crutches d
 Upper Deck Beams & Fastenings d Timbers of the Frame at the Openings d
 Lower Deck Beams & Fastenings d Ditto ditto at other places d
 Planksheers d Keelsons d
 Sheerstrakes d Clamps and Shelves d
 Topsides d Ceiling d
 Sides d Rudder d
 Plank (Bottom) and Counter d Copper or Y.M. — When put on —
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. No plates on port or bottom painted and re-fair in place, and the bottom cleaned and painted. Is in good and efficient condition, and eligible in my opinion to remain as classed

Committee's Minute Friday, March, 5th 1880
 Character assigned 100A1 TRW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid 18

No. 4847 Survey held at Shull Date, first Survey 24 Aug Last Survey 28 Feb 1880
 No. in on the Boa Sen Bg. "Pride" Master —
 Reg. Book. 292 Tonnage 1019 Built at Shull When built 1866 4 mo
 By whom built Shull Owners Brown Atkinson & Co
 Port belonging to Shull Destined Voyage Wattie
 If Surveyed Afloat or in Dry Dock In Ship-way

Last Survey, No. 23081 Port of Dry
 Present Condition of the Decks Good Right When seen Good
 Waterways d Breasthooks and Stemson d
 Comings d Transoms, Pointers, and Crutches d
 Upper Deck Beams & Fastenings d Timbers of the Frame at the Openings d
 Lower Deck Beams & Fastenings d Ditto ditto at other places d
 Planksheers d Keelsons d
 Sheerstrakes d Clamps and Shelves d
 Topsides d Ceiling d
 Sides d Rudder d
 Plank (Bottom) and Counter d Copper or Y.M. — When put on —
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Good on black on ship-way, and the bottom cleaned and painted. Is in good condition & eligible in my opinion to remain as classed.

Committee's Minute Friday, March, 5th 1880
 Character assigned 100A1 TRW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid 18