

26124

Report of Survey for Repairs of Engines and Boilers.

No. 137

(Received at London Office, 4/3/80)

No. in
Reg. Book.

Survey held at Hull

Date, first Survey

24th Jan

Last Survey

24th Jan

1880

18. on the Machinery of the iron screw steamer 'Valthalla'

(Number of Visits One)

Tonnage, Gross

1420

Built at

West Hartlepool

When built

Year

1877

Ditto, Net

919

Owners

J. Herskind

Port belonging to

H. Hartlepool

Year

1877

Diameter of Cylinder

29' + 55'

Engines made by

Richardson & Son, Hartlepool

When made

Year

1877

Length of Stroke

33

Boilers made by

Do

When made

Year

1877

Pressure of Steam

70

If Surveyed Afloat or in Dry Dock

Classed

Years assigned

Character in Register Book.

100 A.1

12.77

Lloyds m.c

12.77

Last Survey No.

Port

Particulars of ~~Repairs~~ and Examination on placing on slipway

To Examined Sea Cocks. Fastenings of same to ship's side found all in good condition

W Propeller examined & hardened up. - cross key & set pins good. - Shaft very little down. - Outer end of stem tube in good condition - Stern gland, new packed.

General Observations, Opinion, and Recommendation:— No repairs to Boilers. Machinery is closed up ready for steaming & treated to be in good working order. - Is eligible in my opinion to remain as classed.

Entry or Registering Fee ... £

Survey Fee ... £

Certificate (if required) ... £

(Travelling Expenses, if any, £)

received by me,

18


John B. Stevens

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Friday, March, 5th 1880

Assigned

Lloyd's Register
Foundation

IRON 491-0321

The cock- propeller &c. of this vessel
have been examined in the ship way
and are reported to be in good
condition submitted that she is
eligible to remain as cleared.

M 4. 3. 80



© 2019

Lloyd's Register
Foundation

Report of Survey for Repairs of Engines and Boilers