

REPORT of SURVEY for REPAIRS, &c.

26158

Rec 8/4/80

No. 4304

No. in Survey held at Dundee

Date, first Survey 27th Feb. Last Survey 18th March 1880

Reg. Book.

643 on the S. Prince Oscar

Master Brooks

TONNAGE under Tonnage Deck 1201

Built at N. Harlepool

When built 1864 10

Ditto of Spar Deck, or Awning Deck

Owners S. R. Graves

Port belonging to Liverpool

Ditto of Poop

Residence Liverpool

Ditto of Raised Qr. Dk.

By whom built Rle

Destined Voyage Bombay via Suez

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage 1292

Crew Space, as per Rule

Register Tonnage, out on Beam 1292

Engine Room

Reg. Tons as St'mer, out on Bm.

Length of Poop - ft. Ditto, Forecastle - ft. Ditto, Raised Quarter Deck - ft. Years assigned. Character in Register Book.

Last Survey, No. 26157 Port Suez

REPAIRS, OR EXAMINATION AS PER RULE Damage

This vessel when near the end of her just now completed passage from Calcutta to this port met with terrific weather - which carried away a prod portion of her topgallant bulwarks - split the main rail on the port side & did considerable damage to deck houses, after cabin &c and to the deck fittings brts davits & stanchions. These have all been now repaired or renewed where required so as to make the vessel as before.

Two brts renewed & several iron stanchions in bulwarks re-riveted. Main topmast sprung & now renewed of pitch pine - Rigging & running gear overhauled & made good.

She has now been placed in graving dock & the bottom cleaned & re-coated.

Present Condition of the

Decks	grd	Ironails Parting	grd	Windlass and Capstan	Complete	grd
Waterways	"	Breasthooks and Stemson	"	Pumps	"	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats 2 new	"	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	inspected	"
Planksheers	"	Keelsons	"	Sails	complete	"
Sheerstrakes	"	Clamps and Shelves	"	Anchor No. of 3/3	15	24
Topsides	"	Ceiling	"	Cables	complete	"
Wales	"	Rudder	"	Hawsers and Warps	grd	"
Plank (Bottom) and Counter	"	Copper Cement When put on	64	Standing & Running Rigging	"	"
Engine Room Skylights	"	Caulking of	"	Cargo and Main Hatchways	grd	Hatches
Coal Bunker, Openings, Lids, &c.	"	Bottom, Deck, & Waterways	grd			
General Observations, Opinion as to Class, &c.		Scuppers	grd			

General Observations, Opinion as to Class, &c.

This vessel is now in good condition & eligible for service, to remain as classed.

The Amount of Entry Fee£

received by me,

Special£ 2 : 2 : 0

1st April 1880

Certificate (if required)£

(Travelling Expenses, if any, £)

Committee's Minute Friday, April, 9th 18 80

Character assigned

Geo. V. Cooper
Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON 491-0367

The Surveyors are requested not to write on or below the space for Committee's Minute.