

# REPORT of SURVEY for REPAIRS, &c.

(Received at London Office, 13: 4. 80)

No. 29046

No. in Survey held at London  
Reg. Book.

Date, first Survey 22<sup>nd</sup> March Last Survey 8<sup>th</sup> April 1880.

84 on the BK. "Saint Mar rock"

Master A. Burd

YEAR. MONTH.

TONNAGE under Tonnage Deck 1193

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St<sup>r</sup>mer, cut on Bm.

1258

1258

Built at Liverpool

When built

1867

6<sup>th</sup>

Owners Parkin Gilmore & Co.

Port belonging to Glasgow

Residence

By whom built Royden

Destined Voyage Calcutta

Surveyed Afloat 2 in Dry Dock Cubitt Town Dry Dock

(State Name of Dock)

Length of Poop ft. Ditto, Forecastle ft.

Ditto, Raised Quarter Deck ft.

ft.

Years assigned.

Character in Register Book.

Last Survey, No. 23235

Port Iron

Classed

\*A1

3.79

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

S. S. Lon. No 2-76

Special Survey No 3.

The vessel placed on blocks in dry dock; stages made; the hold cleared; all the close ceiling in hold removed; all oxidation removed off the iron; cement on inner surface of bottom plating tested & found sound & adhering satisfactorily to the iron.

Masts, spars & general equipment found in good and efficient condition.

Plating, floors, frames etc. recemented or coated with cement wash. - Some defective ceiling renewed. - Foretopgallant yard renewed.

Rig altered to Barque.

Bottom cleaned & repainted.

Present Condition of the

| Decks                            | Good | Good   | Good        | Good  |
|----------------------------------|------|--|-------------|---|
| Waterways                        | do   | Treenails-Rivets                                   | do          | Windlass and Capstan                            |
| Comings                          | do   | Breasthooks and Stenson                            | do          | Pumps   |
| Upper Deck Beams & Fastenings    | do   | Transoms, Pointers, and Crutches                   | do          | Boats <u>4</u> in number                        |
| Lower Deck Beams & Fastenings    | do   | Timbers of the Frame at the openings               | do          | Masts, Yards, &c.                               |
| Planksheers                      | do   | Ditto Ditto at other places                        | do          | Condition, how ascertained <u>aloft sounded</u> |
| Sheerstrakes                     | do   | Keelsons   | do          | Sails <u>well found</u>                         |
| Topsides                         | do   | Clamps and Shelves                                 | do          | Anchors No. of <u>3 B. 1 St. 2 H</u>            |
| Wales                            | do   | Ceiling  | do          | Cables <u>part seen</u>                         |
| Plating (Bottom) and Counter     | do   | Rudder   | do          | Hawsers and Warps                               |
| Engine Room Skylights            | do   | Copper <u>on r.m.</u> Paint When put on <u>now</u> | do          | Standing & Running Rigging                      |
| Coal Bunker, Openings, Lids, &c. | do   | Caulking of  | do          | Cargo and Main Hatchways <u>good</u> Hatches    |
|                                  | do   | Bottom, Deck, & Waterways                          | <u>good</u> |   |
|                                  | do   | Scuppers   | do          |   |

General Observations, Opinion as to Class, &c.

This vessel is in good condition; the requirements of the Survey have been complied with & she is eligible, in our opinion, to remain as classed and to have recorded: S. S. Lon. No 3-80.

The Amount of Entry Fee ... £ 5/4/80 Special ... £ 6:7:0 received by me, 21/4/80

Certificate (if required) to be sent as per margin... £ 5:0

(Travelling Expenses, if any, £)

Committee's Minute

Friday, April, 16th 1880

Character assigned

T.B.W.

S. S. No 3-80

W. Paulsen  
W. B. Dacey  
Senhouse Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping



© 2019

Lloyd's Register Foundation