

ANNUAL SURVEYS.

No. 39019 Survey held at London Date, first Survey March 22 Last Survey April 18 1880
 No. in Reg. Book 116 on the S Old Kensington Master
 Tonnage 1779 Built at Liverpool When built 1874-10
 By whom built Potter Owners Smith Bilbrough & Co.
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Blackwall Point Dry Dock

Last Survey, No. 23343 Port of Iron

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>	Classed	<u>100 A 4.75</u>	Years assigned.	<u>SS Lon M-75</u>	Character in Register Book.
Waterways	"	Breasthooks and Stemson	"	"	Windlass and Capstan	<u>Good</u>			
Comings	"	Transoms, Pointers, and Crutches	"	"	Pumps	"			
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Boats	"			
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Masts, Yards, &c.	"			
Planksheers	"	Keelsons	"	"	Condition, how ascertained	<u>From SK</u>			
Sheerstrakes	"	Clamps and Shelves	"	"	Sails	<u>Good</u>			
Topsides	"	Ceiling	"	"	Anchors, No. of	<u>3 Bns. SK & Redys</u>			
Wales	"	Rudder	"	"	Cables	<u>Part on SK</u>	<u>Good</u>		
Plank (Bottom) and Counter	"	Copper or Y.M. Coated When put on	<u>Now</u>		Hawsers and Warps	"			
Engine Room Skylights		Caulking of			Standing and Running Rigging	"			
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways	<u>Good</u>		Cargo and Main Hatchways	<u>Good</u>			
General Observations, Opinion as to Class, &c.	<u>Bottom & coated</u>								

She is now in good condition and eligible to remain as classed

Committee's Minute Tuesday, April, 13th 1880.

Character assigned 100 A 1 TRW

Senhouse Martinide
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. Survey held at London Date, first Survey March 13 Last Survey April 3 1880
 No. in Reg. Book 460 on the S Plassey Master Pickaby
 Tonnage 1083 Built at Sunderland When built 1874-5
 By whom built Pile Owners G & Tyser & Co.
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Blackwall Point Dry Dock

Last Survey, No. 22945 Port of Iron

Present Condition of the	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>	Classed	<u>100 A 3.75</u>	Years assigned.	<u>SS Lon M-75</u>	Character in Register Book.
Decks	"	Breasthooks and Stemson	"	"	Windlass and Capstan	<u>Good</u>			
Waterways	"	Transoms, Pointers, and Crutches	"	"	Pumps	"			
Comings	"	Timbers of the Frame at the Openings	"	"	Boats	"			
Upper Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Masts, Yards, &c.	"			
Lower Deck Beams & Fastenings	"	Keelsons	"	"	Condition, how ascertained	<u>From SK</u>			
Planksheers	"	Clamps and Shelves	"	"	Sails	<u>Good</u>			
Sheerstrakes	"	Ceiling	"	"	Anchors, No. of	<u>3 Bns. SK & Redys</u>			
Topsides	"	Rudder	"	"	Cables	<u>Part on SK</u>	<u>Good</u>		
Wales	"	Copper or Y.M. Coated When put on	<u>Now</u>		Hawsers and Warps	"			
Plank (Bottom) and Counter	"	Caulking of			Standing and Running Rigging	"			
Engine Room Skylights		Bottom, Deck, & Waterways	<u>Good</u>		Cargo and Main Hatchways	<u>Good</u>			
Coal Bunkers, Openings, Lids, &c.		Scuppers	<u>Good</u>		Hatches	"			
General Observations, Opinion as to Class, &c.	<u>Bottom & coated</u>								

She is now in good condition and eligible to remain as classed

Committee's Minute Tuesday, April, 13th 1880.

Character assigned 100 A 1 TRW

Senhouse Martinide
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 5/ Paid 10/32/4/88

5 all Kennedy
Plassey



© 2019

Lloyd's Register
Foundation