

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. *No. 288142* Survey held at *London* Date, first Survey *5th Jan* Last Survey *26th Jan* 1880
312 on the *Am. S. S. "Osprey"* Master *Trabs*
 TONNAGE under Tonnage Deck *886*
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Space, as per Rule
 Register Tonnage, out on Beam
 Engines Room
 Reg. Tons as St^rmer, out on Bm. *638*
 Built at *Stockton* When built *1877* 9
 Owners *Gen M^r & Co* Port belonging to *London*
 Residence
 By whom built *Pearse* Destined Voyage *Hamburg*
 If Surveyed Afloat or in Dry Dock *Afloat*
 Length of Poop *ft.* Ditto, Forecastle *ft.* Ditto, Raised Quarter Deck *ft.*
 Last Survey, No. *25335* Port *Don* Classed *100 A 1*
 Character in Register Book. *10. 79*

REPAIRS, OR EXAMINATION AS PER RULE

*One plate on each bow new (damage by ice)
 and one plate on each bow doubled to resist ice*

Present Condition of the	<i>Good</i>	<i>Good</i>	<i>Good</i>	<i>Good</i>
Decks		<i>Good</i>		
Waterways		<i>Good</i>		
Timings		<i>Good</i>		
Upper Deck Beams & Fastenings		<i>Good</i>		
Lower Deck Beams & Fastenings		<i>Good</i>		
Stanchions		<i>Good</i>		
Strakes		<i>Good</i>		
Sides		<i>Good</i>		
Keels		<i>Good</i>		
Bottom (Bottom) and Counter		<i>Good</i>		
Engine Room Skylights	<i>Good</i>	<i>Good</i>	<i>Good</i>	<i>Good</i>
Coal Bunker, Openings, Lids, &c.	<i>Good</i>	<i>Good</i>	<i>Good</i>	<i>Good</i>
General Observations, Opinion as to Class, &c.	<i>She appears in good condition and in my opinion may continue as Classed</i>			

Amount of Entry Fee ... £ ... received by me, *24/6*
 Certificate (if required) ... £ ...
 Shipping Expenses, if any, £ ...

Committee's Minute

Friday, January, 30th 1880

Character assigned

100 A 1

*Letter to Gen. M^r & Co
 13/2/80*

TBW

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON 491-0490