

ANNUAL SURVEYS.

Rev 5/7/80

No. 26970 Survey held at Liverpool Date Apr 15th 1880
 on the Ship "Camana" Master S. Walker
 Tonnage 593 Built at Liverpool When built 1865 - 6 mo
 By whom built Vernon Owners Nicholson & M. Gill
 Port belonging to Liverpool Destined Voyage Valparaiso
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock

Last Survey, No. 23511 Port of Inn

Classed *AI
S.S. Lon No 3-78 5.79

present Condition of the

Good

Freonails

Rivets

Good

Windlass and Capstan

Good

Waterways 4
 Rigs 4
 Upper Deck Beams & Fastenings 4
 Lower Deck Beams & Fastenings 4
 Knees 4
 Strakes 4
 Sides 4
 Ends 4
 Hull (Bottom) and Counter 4

Breasthooks and Stems 4
~~Transoms, Pointers, and Crutches~~ 4
~~Timbers of the Frame~~ 4
 Keelsons 4
~~Clamps and Shelves~~
 Ceiling 4
 Rudder 4
 Copper Cement When put on 65 ft 74

Pumps 4
 Boats 4
 Masts, Yards, &c. 4
 Sails 4
 Anchors No. of 3B - 18 - 2K
 Cables pt seen } Good
 Hawsers and Warps } and
 Standing & Running Rigging sufficient

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good

Bottom sighted, cleaned, and coated with paint and the vessel being now in a good & efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute

Liverpool May 4th 1880

Character assigned

*AI

J. Shilston

Certificate (if required)

No. 1101 Survey held at Liverpool Date Apr 14th 1880
 on the Ship "Hawarden Castle" Master Mathews
 Tonnage 1101 Built at Liverpool When built 1869 - 7 mo
 By whom built Evans Owners Richards, Mills & Co
 Port belonging to Liverpool Destined Voyage San Francisco
 If Surveyed Afloat or in Dry Dock Brunswick Dry Dock

Last Survey, No. 25157 Port of Inn

Classed *AI
S.S. Lon No 2-77 3.79

present Condition of the

Good

Freonails

Rivets

Good

Windlass and Capstan

Good

Waterways 4
 Rigs 4
 Upper Deck Beams & Fastenings 4
 Lower Deck Beams & Fastenings 4
 Knees 4
 Strakes 4
 Sides 4
 Ends 4
 Hull (Bottom) and Counter 4

Breasthooks and Stems 4
~~Transoms, Pointers, and Crutches~~ 4
 Timbers of the Frame 4
 Keelsons 4
~~Clamps and Shelves~~
 Ceiling 4
 Rudder 4
 Copper Cement When put on 69

Pumps 4
 Boats 4
 Masts, Yards, &c. 4
 Sails 4
 Anchors No. of 3B - 18 - 2K
 Cables pt seen } Good
 Hawsers and Warps } and
 Standing & Running Rigging sufficient

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good

Bottom sighted, cleaned and coated with paint and the vessel being now in a good & efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute

Liverpool May 12th 1880

Character assigned

*AI

J. Shilston

Certificate (if required)

Camaria
Havarden
Castle

26970



© 2019

Lloyd's Register
Foundation