

# ANNUAL SURVEYS.

No. 39129 Survey held at Londre Date, first Survey 3<sup>rd</sup> April Last Survey 6<sup>th</sup> April 1882  
 No. in on the S. S. "C. Bella" Master A. Kniesberg  
 Reg. Book. 11 Tonnage 58 Built at Newcastle When built 1865 12<sup>th</sup> mo.  
 By whom built Mitchell Owners J. G. Schmidt  
 Port belonging to Hamburg Destined Voyage Hamburg  
 If Surveyed Afloat or in Dry Dock Union Dry Dock

Last Survey, No. 23392 Port of Londre Classified 211  
 Present Condition of the  
 Decks Good Transoms Rivets Good  
 Waterways do Breasthooks and Stemson do Windlass and Capstan Good  
 Comings do Transoms, Pointers, and Crutches do Pumps do  
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do Boats do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places do Masts, Yards, &c. do  
 Planksheers do Keelsons do Condition, how ascertained found & weighing  
 Sheerstrakes do Clamps and Shelves do Sails do  
 Topsides do Ceiling do Anchors, No. of 3 B. 1 St. 2 H. do  
 Wales do Rudder do Cables port open do  
 Plank (Bottom) and Counter do Copper or Y.M. Paint When put on new Haulers and Warps do  
 Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers do Standing and Running Rigging do  
 General Observations, Opinion as to Class, &c. good Cargo and Main Hatchways good Hatches do

Rudd. plates bisbed. - Bottom cleaned & repainted.  
Vessel is intended to be submitted for S. S. 101 in the course of this year.  
She is in good condition & eligible in my opinion to remain as classed.

Committee's Minute Friday, April 30th 18 82  
 Character assigned 211  
 Surveyor to Lloyd's Register of British and Foreign Shipping  
 Certificate (if required) 18

No.            Survey held at            Date, first Survey            Last Survey             
 No. in on the            Master             
 Reg. Book.            Tonnage            Built at            When built             
 By whom built            Owners             
 Port belonging to            Destined Voyage             
 If Surveyed Afloat or in Dry Dock           

Last Survey, No.            Port of            Classified             
 Present Condition of the  
 Decks            Treenails  
 Waterways            Breasthooks and Stemson            Windlass and Capstan             
 Comings            Transoms, Pointers, and Crutches            Pumps             
 Upper Deck Beams & Fastenings            Timbers of the Frame at the Openings            Boats             
 Lower Deck Beams & Fastenings            Ditto ditto at other places            Masts, Yards, &c.             
 Planksheers            Keelsons            Condition, how ascertained             
 Sheerstrakes            Clamps and Shelves            Sails             
 Topsides            Ceiling            Anchors, No. of             
 Wales            Rudder            Cables             
 Plank (Bottom) and Counter            Copper or Y.M.            When put on            Haulers and Warps             
 Engine Room Skylights            Coal Bunkers, Openings, Lids, &c.            Scuppers            Standing and Running Rigging             
 General Observations, Opinion as to Class, &c.            Cargo and Main Hatchways            Hatches           

Committee's Minute 18  
 Character assigned             
 Surveyor to Lloyd's Register of British and Foreign Shipping  
 Certificate (if required)            18