

ANNUAL SURVEYS.

26319

No. 29130 Survey held at London Date, first Survey April 5th Last Survey April 26th 1880
 No. in on the BK Helen Denny Master N Ruth
 Reg. Book. 261 Tonnage 728 Built at St Glasgow When built 1866. 11M
 By whom built Juncan Owners Shaw Saville & Co
 Port belonging to Southampton Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Greens Dry St

Last Survey, No. 23359 Port of Droy
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wals " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom to be coated.
She is now in good condition and eligible to remain as classed.

Classed 7A1 5.75
 I.S. No. 3-72 SS Lon M 2.75

Committee's Minute Friday, April, 30th 1880
 Character assigned *A1
TBW
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. Survey held at London Date, first Survey March 31 Last Survey April 27th 1880
 No. in on the S Eastern Monarch Master J Yates
 Reg. Book. 80 Tonnage 1706 Built at Sunderland When built 1874 - 3M
 By whom built Mounsey Owners Royal Exchange Shipts
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Blackwall Pt Dry St

Last Survey, No. 23573 Port of Droy
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wals " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom to be coated.
She is now in good condition and eligible to remain as classed.

Classed 100A1 5.75
 I.S. No. 3-72 SS Lon M 1.75

Committee's Minute Friday, April, 30th 1880
 Character assigned 100A1
TBW
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18



IRON 492-0026