

ANNUAL SURVEYS.

26327

No. 39175 Survey held at London Date, first Survey 28 April Last Survey 28 April 18 80
 No. in on the BC Oriana Master Brenning
 eg. Book. 23 Tonnage 947 Built at Greenock When built 1864-2
 By whom built Scott Owners Linder, Anderson & Co
 Port belonging to London Destined Voyage A delaide
 If Surveyed Afloat or in Dry Dock Princes dry dock

Last Survey, No. 23425 Port of Iron Classed 1 6.79
 Years assigned. P.P. 4.3.76.
 Character in Register Book.

Present Condition of the Decks

Waterways	<u>de</u>	Transoms, Pointers, and Crutches	<u>de</u>	Windlass and Capstan	<u>de</u>
Comings	<u>de</u>	Timbers of the Frame at the Openings	<u>de</u>	Pumps	<u>de</u>
Upper Deck Beams & Fastenings	<u>de</u>	Ditto ditto at other places	<u>de</u>	Boats	<u>de</u>
Lower Deck Beams & Fastenings	<u>de</u>	Keelsons	<u>de</u>	Masts, Yards, &c.	<u>de</u>
Planksheers	<u>de</u>	Clamps and Shelves	<u>de</u>	Condition, how ascertained	<u>from deck de</u>
Sheerstrakes	<u>de</u>	Ceiling	<u>de</u>	Sails	<u>well found</u>
Topsides	<u>de</u>	Rudder	<u>de</u>	Anchors, No. of	<u>30. 1 S. 8. 20. 20.</u>
Wales	<u>de</u>	Copper or Y.M.	<u>✓</u>	Cables	<u>complete</u>
Plank (Bottom) and Counter	<u>de</u>	Caulking of Bottom, Deck, & Waterways	<u>de</u>	Hawsers and Warps	<u>sufficient</u>
Engine Room Skylights	<u>de</u>	Coal Bunker, Openings, Lids, &c.	<u>de</u>	Standing and Running Rigging	<u>good</u>
General Observations, Opinion as to Class, &c.					

Rudder pintles made good. Bottom cleaned and recoated. This vessel appears eligible to remain as classed. Surveyed with part cargo in hold. It is intended to have two P.S.H.s held on ship's return.

Committee's Minute Tuesday, May, 11th 1880. Thos. Burgess
 Character assigned DTBW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 18

No. 3814 Survey held at London Date, first Survey 28 April Last Survey 28 April 18 80
 No. in on the 13th Gloucester Master Roberts
 eg. Book. 3814 Tonnage 1042 Built at Liverpool When built 1877 12 mo
 By whom built 1049 Owners Williams
 Port belonging to Barnardston Destined Voyage A delaide
 If Surveyed Afloat or in Dry Dock Bridge dry dock

Last Survey, No. 22929 Port of Iron Classed 100 A1
 Years assigned. 3.79
 Character in Register Book.

Present Condition of the Decks

Waterways	<u>de</u>	Transoms, Pointers, and Crutches	<u>de</u>	Windlass and Capstan	<u>de</u>
Comings	<u>de</u>	Timbers of the Frame at the Openings	<u>de</u>	Pumps	<u>de</u>
Upper Deck Beams & Fastenings	<u>de</u>	Ditto ditto at other places	<u>de</u>	Boats	<u>de</u>
Lower Deck Beams & Fastenings	<u>de</u>	Keelsons	<u>de</u>	Masts, Yards, &c.	<u>de</u>
Planksheers	<u>de</u>	Clamps and Shelves	<u>de</u>	Condition, how ascertained	<u>from deck</u>
Sheerstrakes	<u>de</u>	Ceiling	<u>de</u>	Sails	<u>well found</u>
Topsides	<u>de</u>	Rudder	<u>de</u>	Anchors, No. of	<u>20. 1 S. 8. 20. 20.</u>
Wales	<u>de</u>	Copper or Y.M.	<u>✓</u>	Cables	<u>complete</u>
Plank (Bottom) and Counter	<u>de</u>	Caulking of Bottom, Deck, & Waterways	<u>de</u>	Hawsers and Warps	<u>sufficient</u>
Engine Room Skylights	<u>de</u>	Coal Bunkers, Openings, Lids, &c.	<u>de</u>	Standing and Running Rigging	<u>good</u>
General Observations, Opinion as to Class, &c.					

Bottom cleaned and recoated. This vessel appears eligible to remain as classed. Surveyed with part outward cargo in hold.

Committee's Minute Tuesday, May, 11th 1880. Thos. Burgess
 Character assigned 100 A1 DTBW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 18

Orcauer
&
Hampdon



© 2019

Lloyd's Register
Foundation