

ANNUAL SURVEYS. 26387

(Received at London Office, 11/5/80)

No. 3916 Survey held at Sharples Date, first Survey 24 April 1880 Last Survey 24 April 1880
 No. in Reg. Book. 455 on the S. Drumhark Master J. Bailey
 Tonnage 1470 Built at Liverpool When built 1877 7 mo
 By whom built Potter Owners Gillison & Chadwick
 Port belonging to Glasgow Liverpool Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Sharples Dry Dock

Last Survey, No. 21366 Port of London Classed 100 A 1
 Present Condition of the Decks Good 7-70

Waterways	Treenails <u>Rivets</u>	Windlass and Capstan <u>Good</u>
Comings	Breasthooks and Stemson	Pumps
Upper Deck Beams & Fastenings	Transoms, Pointers, and Crutches	Boats
Lower Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Planksheers	Ditto ditto at other places	Condition, how ascertained <u>Iron deck</u>
Sheerstrakes	Keelsons	Sails <u>Good</u>
Topsides	Clamps and Shelves	Anchors, No. of <u>3B 15 2K</u>
Wales <u>Plating</u>	Ceiling	Cables <u>part seen</u> <u>Good</u>
Plank (Bottom) and Counter	Rudder	Hawsers and Warps
Engine Room Skylights	Copper or Y.M. Cement When put on <u>77</u>	Standing and Running Rigging
Coal Bunker, Openings, Lids, &c.	Caulking of Bottom, Deck, & Waterways <u>Good</u>	Cargo and Main Hatchways
Scuppers	Hatches	

General Observations, Opinion as to Class, &c.
Vessel placed in dry dock. her bottom scraped and pointed. Surveyed with ballast lying over greater part of hold. She is now in a good and efficient condition and is eligible in my opinion to remain as classed.

Committee's Minute Tuesday, May, 4th 1880.
 Character assigned 100 A 1
Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRM Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in Reg. Book. _____ on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
 Present Condition of the Decks _____

Waterways	Treenails	Windlass and Capstan
Comings	Breasthooks and Stemson	Pumps
Upper Deck Beams & Fastenings	Transoms, Pointers, and Crutches	Boats
Lower Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Planksheers	Ditto ditto at other places	Condition, how ascertained
Sheerstrakes	Keelsons	Sails
Topsides	Clamps and Shelves	Anchors, No. of
Wales	Ceiling	Cables
Plank (Bottom) and Counter	Rudder	Hawsers and Warps
Engine Room Skylights	Copper or Y.M. When put on	Standing and Running Rigging
Coal Bunkers, Openings, Lids, &c.	Caulking of Bottom, Deck, & Waterways	Cargo and Main Hatchways
Scuppers	Hatches	

General Observations, Opinion as to Class, &c.
 Committee's Minute _____ 18____
 Character assigned _____
Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18____

