

ANNUAL SURVEYS.

26397

No. 29151 Survey held at London Date, first Survey April 26 Last Survey April 27 1880
 No. in on the SS Ferdinand van der Jaalen Master A. Gattoor
 Reg. Book. 168 Tonnage 1114 Built at S Shields When built 1874 6.M
 By whom built S. J. J. J. Owners J. C. Best Barbr
 Port belonging to Antwerp Destined Voyage Cardiff
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 22501 Port of London

Present Condition of the				Classed	Years assigned.	Character in Register Book.
Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>20A1</u>	<u>1.75</u>	<u>SS Gal M177</u>
Waterways	"	Breasthooks and Stemson	"			
Comings	"	Transoms, Pointers, and Crutches	"			
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"			
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"			
Planksheers	"	Keelsons	"			
Sheerstrakes	"	Clamps and Shelves	"			
Topsides	"	Ceiling	"			
Wales	"	Rudder	"			
Plank (Bottom) and Counter	"	Copper or Y.M.	When put on <u>Now</u>			
Engine Room Skylights	<u>Good</u>	Caulking of				
Coal Bunker, Openings, Lids, &c.	<u>Good</u>	Bottom, Deck, & Waterways	<u>Good</u>			
General Observations, Opinion as to Class, &c.	<u>Bottom & counter, a small leak in Puddon Puddon stopped.</u> <u>She is now in good condition</u> <u>and eligible to remain as classed.</u>					

Committee's Minute

Tuesday, May, 4th 1880.

Character assigned

Senhouse Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) 5/1/80 Paid 4/5/80 1880

No. Survey held at Date, first Survey Last Survey 18

No. in on the Reg. Book. Tonnage Built at When built Master
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed

Present Condition of the				Years assigned.	Character in Register Book.
Decks		Treenails			
Waterways		Breasthooks and Stemson			
Comings		Transoms, Pointers, and Crutches			
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings			
Lower Deck Beams & Fastenings		Ditto ditto at other places			
Planksheers		Keelsons			
Sheerstrakes		Clamps and Shelves			
Topsides		Ceiling			
Wales		Rudder			
Plank (Bottom) and Counter		Copper or Y.M.	When put on		
Engine Room Skylights		Caulking of			
Coal Bunkers, Openings, Lids, &c.		Bottom, Deck, & Waterways			
General Observations, Opinion as to Class, &c.					
		Scuppers			
		Cargo and Main Hatchways			
		Hatches			
		Windlass and Capstan			
		Pumps			
		Boats			
		Masts, Yards, &c.			
		Condition, how ascertained			
		Sails			
		Anchors, No. of			
		Cables			
		Hawsers and Warps			
		Standing and Running Rigging			


Committee's Minute

18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18



© 2019

Lloyd's Register Foundation

8210-2611088