

ANNUAL SURVEYS.

26422

No. 25157 Survey held at London Date, first Survey 10 April Last Survey 10 April 1880
 No. in Reg. Book. 179 on the S.S. "Kingston" Master Firth
 Tonnage 922 Built at Sunderland When built 1871
 By whom built Ruswald Owners Commercial Str Co
 Port belonging to London Destined Voyage not known
 If Surveyed Afloat or in Dry Dock Lineholm dry dock

Last Survey, No. 25157 Port of London Classed 90 A 11.79
 Present Condition of the Decks Good Treenails Pivots Good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do Windlass and Capstan Good
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do Pumps two do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do Boats four do
 Planksheers do Keelsons do Masts, Yards, &c. do
 Sheerstrakes do Clamps and Shelves do Condition, how ascertained from deck do
 Topsides do Ceiling do Sails well found
 Wales do Rudder do Anchors, No. of 33. 15 & 12 lbs
 Plank (Bottom) and Counter do Copper or Y.M. ✓ When put on ✓ Cables complete
 Caulking of Bottom, Deck, & Waterways do Standing and Running Rigging good
 Engine Room Skylights do Coal Bunker, Openings, Lids, &c. do Scuppers do Cargo and Main Hatchways do Hatches do
 General Observations, Opinion as to Class, &c.


Bottom cleaned and recoated. This vessel appears in good condition and eligible to remain as classed.

Committee's Minute Tuesday, May, 4th 1880. The London
 Character assigned 90 A 11.79 Surveyor to Lloyd's Register of British and Foreign Shipping.
Sp Damage &c. if Certificate (if required) ✓ Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in Reg. Book. _____ on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Caulking of Bottom, Deck, & Waterways _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c.

Committee's Minute _____ 18 _____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____



Kingston

