

ANNUAL SURVEYS.

26447

No. 39154 Survey held at London Date, first Survey April 26 Last Survey April 30 1880
 No. in on the SS Menzaleh Master N Mearns
 Reg. Book. 454 Tonnage 1267 Built at Stockton When built 1870 - 4
1618 By whom built Pearse Owners Nelson Jonkin & Co
 Port belonging to London Destined Voyage Kurruckee
 If Surveyed Afloat or in Dry Dock Pontoon Victoria St

Last Survey, No. 2552 Port of Iron Classed 20A 12-75
 Years assigned. SS new N277 Character in Register Book.

Present Condition of the	<u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Decks	<u>Good</u>	Breasthooks and Stemson	<u>Good</u>	Pumps	<u>Good</u>
Waterways	<u>Good</u>	Transoms, Pointers, and Crutches	<u>Good</u>	Boats	<u>Good</u>
Comings	<u>Good</u>	Timbers of the Frame at the Openings	<u>Good</u>	Masts, Yards, &c.	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Good</u>	Ditto ditto at other places	<u>Good</u>	Condition, how ascertained	<u>Iron St</u>
Lower Deck Beams & Fastenings	<u>Good</u>	Keelsons	<u>Good</u>	Sails	<u>Good</u>
Planksheers	<u>Good</u>	Clamps and Shelves	<u>Good</u>	Anchors, No. of <u>3 lbs 8 1/2 Hedges</u>	<u>Good</u>
Sheerstrakes	<u>Good</u>	Ceiling	<u>Good</u>	Cables <u>Part in St</u>	<u>Good</u>
Topsides	<u>Good</u>	Rudder	<u>Good</u>	Hawsers and Warps	<u>Good</u>
Wales	<u>Good</u>	Copper or Y.M. <u>Coated</u> When put on <u>Now</u>	<u>Good</u>	Standing and Running Rigging	<u>Good</u>
Plank (Bottom) and Counter	<u>Good</u>	Caulking of	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>
Engine Room Skylights	<u>Good</u>	Bottom, Deck, & Waterways	<u>Good</u>	Hatches	<u>Good</u>
Coal Bunker, Openings, Lids, &c.	<u>Good</u>	Scuppers	<u>Good</u>		

General Observations, Opinion as to Class, &c. Bottom & coated
She is now in good condition and eligible to remain as classed.

Committee's Minute Friday, May, 7th 1880
 Character assigned Good TT3W
Leahouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 1880

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
 Years assigned. Character in Register Book.
 Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned

 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18



IRON 492-0201