

ANNUAL SURVEYS. 26534

No. 39211 Survey held at London Date, first Survey April 16 Last Survey May 7th 1880
 No. in on the BK Jane Porter Master J. Legg
 Reg. Book. 175 Tonnage 953 Built at Belfast When built 1860. 9th
 By whom built Harland Owners J. O. Barry
 Port belonging to Belfast Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 22466 Port of London Classed A Years assigned 1.12.78. Character in Register Book.
 Present Condition of the Decks good Treenails Rivets good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches " Windlass and Capstan good
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Pumps "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Boats "
 Planksheers " Keelsons " Masts, Yards, &c. "
 Sheerstrakes " Clamps and Shelves " Condition, how ascertained From St
 Topsides " Ceiling " Sails good
 Vales " Rudder " Anchors, No. of 3 Bes. St & Wedges
 Plank (Bottom) and Counter " Copper or Y.M. coated When put on now Cables Part on St good
 Engine Room Skylights " Caulking of Bottom, Deck, & Waterways good Hawsers and Warps "
 Coal Bunker, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches "
 General Observations, Opinion as to Class, &c. Bottom ke coated.
She is now in good condition and eligible to remain as classed.

Committee's Minute Friday, May, 21st 1880 Senhouse Martindale
 Character assigned JRW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 600 Survey held at London Date, first Survey April 10th Last Survey April 30th 1880
 No. in on the S Roslin Castle Master Guthrie
 Reg. Book. 600 Tonnage 1170 Built at Glasgow When built 1863. 7
 By whom built Napier Owners J. Currie & Co
 Port belonging to Liverpool Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 21276 Port of London Classed A Years assigned 1.8.79 Character in Register Book.
 Present Condition of the Decks good Treenails Rivets good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches " Windlass and Capstan good
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Pumps "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Boats "
 Planksheers " Keelsons " Masts, Yards, &c. "
 Sheerstrakes " Clamps and Shelves " Condition, how ascertained From St
 Topsides " Ceiling " Sails good
 Vales " Rudder " Anchors, No. of 3 Bes. St & Wedges
 Plank (Bottom) and Counter " Copper or Y.M. coated When put on now Cables Part on St good
 Engine Room Skylights " Caulking of Bottom, Deck, & Waterways good Hawsers and Warps "
 Coal Bunkers, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches "
 General Observations, Opinion as to Class, &c. Bottom ke coated.
She is now in good condition and eligible to remain as classed.

Committee's Minute Friday, May, 21st 1880 Senhouse Martindale
 Character assigned JRW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

Jane Porter
Rochester



© 2019

Lloyd's Register
Foundation