

ANNUAL SURVEYS. 26534

No. 39211 Survey held at London Date, first Survey April 16 Last Survey May 7th 1880
 No. in on the BK Jane Porter Master J. Legg
 Reg. Book. 175 Tonnage 953 Built at Belfast When built 1860. 5th
 By whom built Harland Owners J. O. Barry
 Port belonging to Belfast Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 22466 Port of Dunne
 Present Condition of the
 Decks good Treenails Rivets good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Vales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on new
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches "
 General Observations, Opinion as to Class, &c. Bottom ke coated.
She is now in good condition and eligible to remain as classed.

Committee's Minute Friday, May, 21st 1880
 Character assigned TRW
Senhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 1880

No. 600 Survey held at London Date, first Survey April 10th Last Survey April 30th 1880
 No. in on the S Roslin Castle Master Guthrie
 Reg. Book. 600 Tonnage 1170 Built at Glasgow When built 1863. 7
 By whom built Napier Owners J. Currie & Co
 Port belonging to Liverpool Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 11276 Port of Dun
 Present Condition of the
 Decks good Treenails Rivets good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Vales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on new
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches "
 Observations, Opinion as to Class, &c. Bottom ke coated.
She is now in good condition and eligible to remain as classed.

Committee's Minute Friday, May, 21st 1880
 Character assigned TRW
Senhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 1880

Jane Porter
Rochester, N.Y.



© 2019

Lloyd's Register
Foundation