

ANNUAL SURVEYS. 26599

No. 29144 Survey held at London Date, first Survey 19 April Last Survey 21 April 1880
 No. in on the S.P. Mid Survey Master G. Dobby
 Reg. Book. 1050 Tonnage 581 Built at Newcastle When built 1870
 By whom built Palmer Owners Dixon & Harris
 Port belonging to London Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock London dry dock

Last Survey, No. 23060 Port of Iron Classed 90 A1
 Present Condition of the Decks Good Treenails Plants Good
 Waterways d^c Breasthooks and Stemson d^c
 Comings d^c Transoms, Pointers, and Crutches d^c Windlass and Capstan Good
 Upper Deck Beams & Fastenings d^c Timbers of the Frame at the Openings d^c Pumps d^c
 Lower Deck Beams & Fastenings d^c Ditto ditto at other places d^c Boats Three d^c
 Planksheers d^c Keelsons d^c Masts, Yards, &c. d^c
 Sheerstrakes d^c Clamps and Shelves d^c Condition, how ascertained from deck
 Topsides d^c Ceiling d^c Sails well found
 Wales d^c Rudder d^c Anchors, No. of 310. 1 S & 8 Kedges
 Plank (Bottom) and Counter d^c Copper or Y.M. - When put on - Cables complete
 Engine Room Skylights d^c Coal Bunker, Openings, Lids, &c. d^c Scuppers d^c Cargo and Main Hatchways d^c Hatches d^c
 General Observations, Opinion as to Class, &c.

Bottom recoated and Rudder pintles made good - Ceiling patterns are not fitted in this vessel, she being engaged in the coal trade - This vessel appears eligible to remain as classed

Committee's Minute Tuesday, May, 4th, 1880. Geo. Hodgson
 Character assigned 90 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 5/ Paid 18 May 1880

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in on the _____ Master _____
 Reg. Book. _____ Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____ Windlass and Capstan _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____ Pumps _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____ Boats _____
 Planksheers _____ Keelsons _____ Masts, Yards, &c. _____
 Sheerstrakes _____ Clamps and Shelves _____ Condition, how ascertained _____
 Topsides _____ Ceiling _____ Sails _____
 Wales _____ Rudder _____ Anchors, No. of _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____ Cables _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c.

Committee's Minute _____ 18____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18____



IRON 492-0411

