

ANNUAL SURVEYS.

26636

No. in Reg. Book. *217* No. *29244* Survey held at *London* Date, first Survey *May 18th* Last Survey *May 20th* 18*80*
 on the *Despatch* Master _____
 Tonnage *465* Built at *Newcastle* When built *1863*
 By whom built *Palmer* Owners *J Fenwick & Son*
 Port belonging to *London* Destined Voyage *Coal Trade*
 If Surveyed Afloat or in Dry Dock *Pontoon Victoria St*

Last Survey, No. *23452* Port of *London*

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Treenails *Good* Rivets *as per renewed*

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper or Y.M. *Good*

Caulking of Bottom, Deck, & Waterways

When put on *Good*

Scuppers *Good*

Cargo and Main Hatchways *Good*

Hatches *Good*

Windlass and Capstan *Good*

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained *See SH*

Sails *Good*

Anchors, No. of *3 Bn H & 1 Hedge*

Cables *Part SH*

Hawsers and Warps

Standing and Running Rigging

Sheepers *Good*

Cargo and Main Hatchways *Good*

Hatches *Good*

Windlass and Capstan *Good*

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained *See SH*

Sails *Good*

Anchors, No. of *3 Bn H & 1 Hedge*

Cables *Part SH*

Hawsers and Warps

Standing and Running Rigging

Sheepers *Good*

Cargo and Main Hatchways *Good*

Hatches *Good*

Windlass and Capstan *Good*

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained *See SH*

Sails *Good*

Anchors, No. of *3 Bn H & 1 Hedge*

Cables *Part SH*

Hawsers and Warps

Standing and Running Rigging

Sheepers *Good*

Cargo and Main Hatchways *Good*

Hatches *Good*

Windlass and Capstan *Good*

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained *See SH*

Sails *Good*

Anchors, No. of *3 Bn H & 1 Hedge*

Cables *Part SH*

Hawsers and Warps

Standing and Running Rigging

Sheepers *Good*

Cargo and Main Hatchways *Good*

Hatches *Good*

Classed

Years assigned.

Character in Register Book.

C

1

5.78

SS New

M23.78

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Committee's Minute

Tuesday, June, 1st 1880.

Character assigned

FC

DBW

Senhouse Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

No.

Survey held at

Date, first Survey

Last Survey

18

No. in Reg. Book. on the

Master

Tonnage

Built at

When built

By whom built

Owners

Port belonging to

Destined Voyage

If Surveyed Afloat or in Dry Dock

Last Survey, No.

Port of

Classed

Years assigned.

Character in Register Book.

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunkers, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper or Y.M.

When put on

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Committee's Minute

18


Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18



© 2019

Lloyd's Register

Foundation

17940-2641001

ANNUAL SURVEYS



© 2019

Lloyd's Register
Foundation

Beal/John