

ANNUAL SURVEYS.

26638

No. in Reg. Book. No. 39,240 Survey held at London Date, first Survey May 15th Last Survey May 28th 18 80
SS Henry Morton Master J G Douglas
 Tonnage 786 Built at Newcastle When built 1860. 10m
 By whom built Palmer Owners J Gennick & Son
 Port belonging to London Destined Voyage Coal Trade
 If Surveyed Afloat or in Dry Dock Pontoon Victoria St

Last Survey, No. 24384 Port of Don Classed Δ 18.75
 Years assigned. SS Don 18.75 Character in Register Book.

Present Condition of the Decks Good Treenails Pivots Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on new
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom is coated

She is now in good condition and eligible to remain as classed.

Committee's Minute Tuesday, June, 1st 18 80. Senhouse Martindale
 Character assigned TRW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18 80

No. Survey held at Date, first Survey Last Survey 18
 No. in Reg. Book. on the Master
 Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
 Years assigned. Character in Register Book.
 Present Condition of the Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

IRON 492-0467

Henry Martin

ANNUAL SURVEYS



© 2019

Lloyd's Register
Foundation