REPORT of SURVEY for REPAIRS, &c.

No. 3258 — 24665 — Ke 22/12/79

No. in Reg. Book. 1445 — Survey held at Aberdeen — Date, first Survey Nov 22 — Last Survey Dec 15 18 79

on the Dec Jan 23 — Master Stephen (YEAR. MONTH.)

Official Number 84515

TONNAGE under Tonnage Deck	262.		
Ditto of Spar Deck, or Awning Deck		Built at	Aberdeen — When built 1872.
Ditto of Poop			
Ditto of Raised Qr. Dk.		Owners	Adam & Co — Port belonging to Aberdeen
Ditto of Houses on Deck			
Ditto of Forecastle		Residence	Aberdeen
Gross Tonnage	304.		
Crew Space, as per Rule		By whom built	A Hall & Co — Destined Voyage Coasting
Register Tonnage, cut on Beam			
Engine Room		If Surveyed Afloat or in Dry Dock	On a patent slip & afloat
Reg. Tons as St'mer, cut on Bm.	196.		

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. — Years assigned. — Character in Register Book.

Classed — 90 A 1

Last Survey, No. 24110 Port Ton — 1 Oct 1876 90 A 1 — 1 Oct 1878 ~~9 A 1~~ — 1 Oct 1879 7.79

REPAIRS, OR EXAMINATION AS PER RULE

Renewed about 000 feet of Ceiling of Norway Red Pine, and about 300 feet of flat of Raised Quarter Deck 3 & 6 Pitch Pine renewed & renew Boiler, cement in flat of bottom renewed where found broken or wasted. Caulked part of deck, Coated bottom Boiler removed, and the various parts of the vessel under ditto carefully examined and found to be in good condition.

Renewed Boiler

Present Condition of the

Decks	Good part new	Rivets		Windlass and Capstan	Good
Waterways	Good	Treenails	Good	Pumps	of Iron efficient
Comings	"	Breasthooks and Sternson	"	Boats	2 "
Upper Deck Beams & Fastenings	"	Transoms, Pointers, and Crutches	"	Masts, Yards, &c.	Good
Lower Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Condition, how ascertained	from examination and enquiry
Planksheers	"	Ditto Ditto at other places	"	Sails	Good
Sheerstrakes	"	Keelsons	"	Anchors No. of	2 Bower 1 Stream 1 Kedge
Topsides	"	Clamps and Shelfs	"	Cables	Good
Wales	"	Ceiling	Good part new	Hawsers and Warps	" and sufficient
Plank (Bottom) and Counter	"	Rudder	Good	Standing & Running Rigging	"
		~~Copper~~ When put on			
		Caulking of Bottom, Deck, & Waterways	Good where tested		

Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c. This vessel appears on examination to be in good and efficient condition and is eligible in my opinion to remain as classed 90 A 1

The Amount of Entry Fee ... ...£ : : received by me, J. W. Kettle Dec 20 1879

Special ... ...£ 2 : 2 : 0

Certificate (if required) ... ...£ : 2 : 6

(Travelling Expenses, if any, £ None)

J. W. Kettle

Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute 23rd December, 1879.

Character assigned 90 A 1

Examd JBW

Causes of Repairs to be clearly stated.

© 2019 Lloyd's Register Foundation

HKN492-0509