

REPORT of SURVEY for REPAIRS, &c.

No. 5100

No. in Survey held at Glasgow
Reg. Book.

Date, first Survey 19 May

(Received at London Office, 3/6/80)
Last Survey 28 May 1880

6257 on the Ship "Loch Tennacher"

Master Czanne

Official Number 4748
TONNAGE under Tonnage Deck 1362
Ditto of Spar Deck, or Awning Deck
Ditto of Poop
Ditto of Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecas.
Gross Tonnage 1557
Crew Space, as per Rule
Register Tonnage, cut on Beam 1485
Engine Room
Reg. Tons as St^rmer, cut on Bm.

Built at Glasgow

When built 1875-8

Owners Glas. Sh. Co.

Port belonging to Glasgow

Residence 80 Buchanan Street Glasgow

By whom built Thomson

Destined Voyage Melbourne

If Surveyed Afloat or in Dry Dock

Afloat

Length of Poop - ft. Ditto, Forecastle - ft.

Ditto, Raised Quarter Deck - ft.

Years assigned.

Character in Register Book.

Last Survey, No. 23819

Port Iron

Classed

100A1
6-79.

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

*The timber boards and all ceiling hatches removed
Cement increased in thickness from bilge to bilge all fore
and aft. Iron work examined and found in good condition
This vessel will be docked in Melbourne to clean and
paint the bottom*

Present Condition of the

Decks	Good	Timber	Paints	Good	Windlass and Capstan	Good
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	<u>4</u>
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	<u>Examined</u>
Plank sheers	"	Keelsons	"	"	Sails	<u>Two Suits Good</u>
Sheerstrakes	"	Champs and Stetfs	"	"	Anchors No. of	<u>3 B. 1 S. 2 W</u>
Topsides	"	Ceiling	"	"	Cables	<u>Good</u>
Wales	"	Rudder	"	"	Hawsers and Warps	<u>and</u>
Plank (Bottom) and Counter	"	Copper (or st.) Cement When put on	<u>Pt now</u>	"	Standing & Running Rigging	<u>Sufficient</u>
Engine Room Skylights	"	Caulking of	"	"	Cargo and Main Hatchways	<u>Good</u>
Coal Bunker, Openings, Etc., &c.	"	Bottom, Deck, & Waterways	<u>Good</u>	"	Hatches	<u>Good</u>
Scuppers	<u>Good</u>					

General Observations, Opinion as to Class, &c.

*This vessel as far as can be seen afloat is now in good
condition in my opinion eligible to remain as Classed
and to be marked in the Register Book S. S. No 1-1880*

The Amount of Entry Fee ... £ 4 : 7 : 6 received by me, J. Lawrence

Special ... £ 3 : 3 : 0 June 1880

Certificate (if required)
to be sent as per margin... £ 7 : 7 : 0

Travelling Expenses, if any, £ ✓

Committee's Minute

Friday, June, 4th 1880

Character assigned

100A1
JBW S. S. No 1-80

Surveyor to Lloyd's Register of British and Foreign Shipping.

Melbourne
144
Record
Docked at Melbourne

IRON 492-0529