

8/6/80

## ANNUAL SURVEYS.

26732

No. 2927

Survey held at

London

Date, first Survey

May 31<sup>st</sup>

Last Survey

June 1<sup>st</sup>

1880

No. in on the

SS Seine

Master

Manning

Reg. Book.

Tonnage

2200

Built at

London

When built

1855

By whom built

James Ship &amp;

Owners

Tel Bon &amp; Maint Co.

Port belonging to

London

Destined Voyage

Sailing in the River London &amp; Sea

If Surveyed Afloat or in Dry Dock

Last Survey, No.

2473

Port of

London

Present Condition of the

Decks

Good

Treenails

Rivets

Good

Waterways

"

Breasthooks and Stemson

"

Comings

"

Transoms, Pointers, and Crutches

"

Upper Deck Beams &amp; Fastenings

"

Timbers of the Frame at the Openings

"

Lower Deck Beams &amp; Fastenings

"

Ditto ditto at other places

"

Planksheers

"

Keelsons

"

Sheerstrakes

"

Clamps and Shelves

"

Topsides

"

Ceiling

"

Wales

"

Rudder

"

Plank (Bottom) and Counter

"

Copper or Y.M. Coated When put on

Caulking of

Bottom, Deck, &amp; Waterways

Good

Engine Room Skylights

Good

Coal Bunker, Openings, Lids, &amp;c.

Good

Scuppers

Good

Cargo and Main Hatchways

Good

Hatches

General Observations, Opinion as to Class, &amp;c.

Bottom &amp;c scraped &amp; coated

She is now in good condition  
and eligible to remain as classed.

Committee's Minute

Friday June 4<sup>th</sup> 1880

Character assigned

100A

Senhouse Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

No.

Survey held at

Date, first Survey

Last Survey

18

No. in on the

Master

Reg. Book.

Tonnage

Built at

When built

By whom built

Owners

Port belonging to

Destined Voyage

If Surveyed Afloat or in Dry Dock

Last Survey, No.

Port of

Classed

Years assigned.

Character in Register Book.

Present Condition of the

Decks

Treenails

Waterways

Breasthooks and Stemson

Comings

Transoms, Pointers, and Crutches

Upper Deck Beams &amp; Fastenings

Timbers of the Frame at the Openings

Lower Deck Beams &amp; Fastenings

Ditto ditto at other places

Planksheers

Keelsons

Sheerstrakes

Clamps and Shelves

Topsides

Ceiling

Wales

Rudder

Plank (Bottom) and Counter

Copper or Y.M.

When put on

Caulking of

Bottom, Deck, &amp; Waterways

Engine Room Skylights

Coal Bunkers, Openings, Lids, &amp;c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &amp;c.

Committee's Minute

18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18