

## ANNUAL SURVEYS.

26754

No. 3222 Survey held at London Date, first Survey 13<sup>th</sup> May Last Survey 13<sup>th</sup> May 1880  
 No. in on the Ship "Bannockburn" Master J. Young  
 Reg. Book. 70 Tonnage 1675 Built at Greenock When built 1875 4<sup>th</sup>.  
 By whom built Steel Owners R. Shankland & Co.  
 Port belonging to Greenock Destined Voyage Liverpool & East Indies  
 If Surveyed Afloat or in Dry Dock Cubitt Town Dry Dock

Last Survey, No. 24333 Port of Iron

Classed

Years assigned.

Character in Register Book.

100 A1

8.79

Present Condition of the

Decks

Good

Treenails

Rivets

Good

Waterways

do

Breasthooks and Stemson

do

Comings

do

Transoms, Pointers, and Crutches

do

Upper Deck Beams &amp; Fastenings

do

Timbers of the Frame at the Openings

do

Lower Deck Beams &amp; Fastenings

do

Ditto ditto at other places

do

Planksheers

do

Keelsons

do

Sheerstrakes

do

Clamps and Shelves

do

Topsides

do

Ceiling

do

Wales

do

Rudder

do

Plank (Bottom) and Counter

do

Copper or Y.M. Paint When put on now

Engine Room Skylights

Coal Bunker, Openings, Lids, &amp;c.

Scuppers

do

Cargo and Main Hatchways

good

Hatches

do

General Observations, Opinion as to Class, &amp;c.

Rudder pintles bushed. Bottom cleaned & repainted.  
 Surveyed with ballast in hold in way of main hatch

She is in good condition & eligible in my opinion to remain as classed.

Committee's Minute

Friday, May, 28<sup>th</sup> 18 80

W. Taulsen.

Character assigned

100 A1

TRW

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

No. Survey held at London Date, first Survey 15<sup>th</sup> May Last Survey 15<sup>th</sup> May 1880

No. in on the Ship "Blairhoy" Master Watson  
 Reg. Book. 499 Tonnage 1291 Built at Glasgow When built 1875 11<sup>th</sup>  
 By whom built Connell Owners Dickie & Co.  
 Port belonging to Glasgow Destined Voyage Cardiff  
 If Surveyed Afloat or in Dry Dock Britannia Dry Dock

Last Survey, No. 22609 Port of Iron

Classed

Years assigned.

Character in Register Book.

100 A1

1.79

Present Condition of the

Decks

Good

Treenails

Rivets

Good

Waterways

do

Breasthooks and Stemson

do

Comings

do

Transoms, Pointers, and Crutches

do

Upper Deck Beams &amp; Fastenings

do

Timbers of the Frame at the Openings

do

Lower Deck Beams &amp; Fastenings

do

Ditto ditto at other places

do

Planksheers

do

Keelsons

do

Sheerstrakes

do

Clamps and Shelves

do

Topsides

do

Ceiling

do

Wales

do

Rudder

do

Plank (Bottom) and Counter

do

Copper or Y.M. Paint When put on now

Engine Room Skylights

Coal Bunkers, Openings, Lids, &amp;c.

Scuppers

do

Cargo and Main Hatchways

good

Hatches

do

General Observations, Opinion as to Class, &amp;c.

Rudder pintles bushed. Bottom cleaned & repainted.  
 Surveyed with ballast in hold in way of main hatch.

She is in good condition & eligible in my opinion to remain as classed.

Committee's Minute

Friday, May, 28<sup>th</sup> 18 80

Character assigned

100 A1

TRW

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

Wm Lloyd Garrison  
to  
Plainsboro

