

ANNUAL SURVEYS.

26792

(Received at London Office, 8.6.88)

No. 29245 Survey held at London Date, first Survey 27th May Last Survey 28th May 1880.
 No. in on the Ship "Serapis" Master A. Parkhurst
 Reg. Book. 546 Tonnage 995 1027 933 Built at Greenock When built 1876 11th
 By whom built J. L. Scott Owners W. Lund
 Port belonging to London Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock Regents Dry Dock

Last Survey, No. 22855 Port of Iron Classed 100 A1
 Years assigned. 2.79 Character in Register Book.
 Present Condition of the Decks Good Treenails Rivets Good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Wales do Rudder do
 Planks (Bottom) and Counter do Copper or F.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights do Coal Bunker, Openings, Lids, &c. do Scuppers do Cargo and Main Hatchways good Hatches do
 General Observations, Opinion as to Class, &c.

Bottom cleaned & repainted.
Surveyed with ballast in hold in way of main hatch.
The owner desires to postpone S. S. No 1 until vessels return from her intended voyage.

She is in good condition & eligible in my opinion to remain as classed.
 Committee's Minute Friday, June, 11th 1880
 Character assigned 100 A1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 18

No. 889 Survey held at London Date, first Survey 31st May Last Survey 31st May 1880.
 No. in on the Bk. "Lurline" Master J. Adair
 Reg. Book. 889 Tonnage 761 800 703 Built at Glasgow When built 1877 2nd
 By whom built Stephen Owners J. Adair
 Port belonging to Glasgow Destined Voyage Otago
 If Surveyed Afloat or in Dry Dock Culitt Town Dry DK

Last Survey, No. 23099 Port of Iron Classed 100 A1
 Years assigned. 4.79 Character in Register Book.
 Present Condition of the Decks Good Treenails Rivets Good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Wales do Rudder do
 Planks (Bottom) and Counter do Copper or F.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights do Coal Bunkers, Openings, Lids, &c. do Scuppers do Cargo and Main Hatchways good Hatches do
 General Observations, Opinion as to Class, &c.

Bottom cleaned & repainted.
Surveyed with ballast in hold all fore & aft.

She is in good condition & eligible in my opinion to remain as classed.
 Committee's Minute Friday, June, 11th 1880
 Character assigned 100 A1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 18

