

ANNUAL SURVEYS. 26808

No. 39289 Survey held at London Date, first Survey June 1st Last Survey June 7th 18 80
(Received at London Office, 12. 6. 80)
 No. in on the SS Europa Master A Munroe
 Reg. Book. 1016 Tonnage 605 Built at Newcastle When built 1862-3M
 By whom built Palmer Owners Son Steu Ship Co.
 Port belonging to London Destined Voyage Mediterranean
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock

Last Survey, No. 24383 Port of Iron Classed 95 A. 8. 75
Years assigned. Character in Register Book.
 Present Condition of the Decks Good Treenails Rivets Good P.L. No. 3-7585 Lin No. 1-75
 Waterways Good Breasthooks and Stemson Good Windlass and Capstan Good
 Comings Good Transoms, Pointers, and Crutches Good Pumps Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good Boats Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good Masts, Yards, &c. Good
 Planksheers Good Keelsons Good Condition, how ascertained Inspected
 Sheerstrakes Good Clamps and Shelves Good Sails Good
 Topsides Good Ceiling Good Anchors, No. of 2 Nos. 12 & 14 lbs
 Wales Good Rudder Good Cables Part on 12 Good
 Plank (Bottom) and Counter Good Copper or Y.M. Copper When put on Now Hawser and Warps Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom to be coated

She is now in good condition and eligible to remain as classed

Committee's Minute Tuesday, June, 15th, 1880. Senhouse Martindale
 Character assigned 95 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) DTW Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
 No. in on the _____ Master _____
 Reg. Book. _____ Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
Years assigned. Character in Register Book.
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18 _____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____



Europa

