

ANNUAL SURVEYS.

26821

No. 39308 Survey held at London Date, first Survey 25 May Last Survey 25 May 1880
 No. in on the S.S. Thunder Master Barlyon
 Reg. Book. late Pannusula
308 Tonnage 577 Built at London When built 1853
 By whom built _____ Owners J. Watkins
 Port belonging to London Destined Voyage Christiana
 If Surveyed Afloat or in Dry Dock Lineholm dry dock

(Received at London Office, 4 26 80)

Last Survey, No. 24459 Port of Don Classed _____ Years assigned _____ Character in Register Book. 80 A 7 79
S.P.N. 3.76 N. 1.79

Present Condition of the Decks _____	<u>Good</u>	Treenails <u>Quiet</u>	<u>Good</u>
Waterways _____	<u>do</u>	Breasthooks and Stemson _____	<u>do</u>
Comings _____	<u>do</u>	Transoms, Pointers, and Crutches _____	<u>do</u>
Upper Deck Beams & Fastenings _____	<u>do</u>	Timbers of the Frame at the Openings _____	<u>do</u>
Lower Deck Beams & Fastenings _____	<u>do</u>	Ditto ditto at other places _____	<u>do</u>
Planksheers _____	<u>do</u>	Keelsons _____	<u>do</u>
Sheerstrakes _____	<u>do</u>	Clamps and Shelves _____	<u>do</u>
Topsides _____	<u>do</u>	Ceiling _____	<u>do</u>
Wales _____	<u>do</u>	Rudder _____	<u>do</u>
Plank (Bottom) and Counter _____	<u>do</u>	Copper or Y.M. _____ When put on _____	
Engine Room Skylights <u>do</u>		Caulking of Bottom, Deck, & Waterways _____	
Coal Bunker, Openings, Lids, &c. <u>do</u>		Scuppers <u>do</u>	Cargo and Main Hatchways <u>do</u>
Hatches <u>do</u>			

Windlass and Capstan Good
 Pumps do
 Boats three do
 Masts, Yards, &c. do
 Condition, how ascertained from deck
 Sails well found
 Anchors, No. of 3 No. 15 kedges
 Cables complete
 Hawseers and Warps sufficient
 Standing and Running Rigging good

General Observations, Opinion as to Class, &c. _____

Bottom cleaned and recoated. This vessel appears eligible to remain as classed.

Committee's Minute _____ Tuesday, June, 22nd. 1880, J. B. Bougdon
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____


No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
 No. in on the _____ Master _____
 Reg. Book. _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____ Years assigned _____ Character in Register Book. _____

Present Condition of the Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Condition, how ascertained _____
Planksheers _____	Keelsons _____	Sails _____
Sheerstrakes _____	Clamps and Shelves _____	Anchors, No. of _____
Topsides _____	Ceiling _____	Cables _____
Wales _____	Rudder _____	Hawseers and Warps _____
Plank (Bottom) and Counter _____	Copper or Y.M. _____ When put on _____	Standing and Running Rigging _____
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways _____	
Coal Bunkers, Openings, Lids, &c. _____	Scuppers _____	Cargo and Main Hatchways _____
Hatches _____		

General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18 _____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____



Thunder



© 2019

Lloyd's Register
Foundation