

# ANNUAL SURVEYS.

26836  
Dec 21/6/80

No. 625 Survey held at Antwerp Date 9-11 Decr 1880.  
 on the Shoon L.S. Helge Master Heathhiser  
 Tonnage 527 Built at Thompson When built 1869 - 5<sup>th</sup> class  
 By whom built Henderson Owners Steamship Co. Dannebrog  
 Port belonging to Helsingfors Destined Voyage Anten - Baltic  
 If Surveyed Afloat or in Dry Dock in dry dock

Last Survey, No. 21172 Port of Iron Classed B. 1.

present Condition of the  
good  
 Treenails Hiets good  
 Breasthooks and Stemson "  
 Transoms, Pointers, and Crutches "  
 Timbers of the Frame at the Openings "  
 Ditto ditto at other places "  
 Keelsons "  
 Clamps and Shelves "  
 Ceiling "  
 Rudder "  
 Copper Paint When put on new  
 Windlass and Capstan good  
 Pumps "  
 Boats "  
 Masts, Yards, &c. "  
 Sails "  
 Anchors, No. of 6  
 Cables suff. in size & length  
 Hawesers and Warps good  
 Standing and Running Rigging "

General Observations and Opinion,  
Shored in dry dock and surveyed all outside & inside as far as practicable  
and found when in good condition for service &c. please see Engr-  
Surveyors Report. Cleaned & repaired bottom. The vessel is in very  
good condition and  
worthy for further service.

Committee's Minute Tuesday, June, 22nd. 18 80.  
 Character assigned B 1  
B & M S. b. 80 JBW  
 For received L.S. 2.0. 5  
 Certificate if required. yes

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

present Condition of the  
 Treenails \_\_\_\_\_  
 Breasthooks and Stemson \_\_\_\_\_  
 Transoms, Pointers, and Crutches \_\_\_\_\_  
 Timbers of the Frame at the Openings \_\_\_\_\_  
 Ditto ditto at other places \_\_\_\_\_  
 Keelsons \_\_\_\_\_  
 Clamps and Shelves \_\_\_\_\_  
 Ceiling \_\_\_\_\_  
 Rudder \_\_\_\_\_  
 Copper \_\_\_\_\_ When put on \_\_\_\_\_  
 Windlass and Capstan \_\_\_\_\_  
 Pumps \_\_\_\_\_  
 Boats \_\_\_\_\_  
 Masts, Yards, &c. \_\_\_\_\_  
 Sails \_\_\_\_\_  
 Anchors, No. of \_\_\_\_\_  
 Cables \_\_\_\_\_  
 Hawesers and Warps \_\_\_\_\_  
 Standing and Running Rigging \_\_\_\_\_

General Observations and Opinion,  
 Committee's Minute \_\_\_\_\_ 18\_\_\_\_  
 Character assigned \_\_\_\_\_  
 Certificate (if required). \_\_\_\_\_