

ANNUAL SURVEYS.

No. 29316 Survey held at London Date, first Survey 15 May Last Survey 9 June 1880
 No. in Reg. Book. 107 on the S. "Barossa" Master Walker
 Tonnage 968 Built at Sunderland When built 1843-5
 By whom built Pile Owners J. B. Walker
 Port belonging to London Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock Lincolnton dry dock

Last Survey, No. 23560 Port of London Classed 100 A1 5.79
 Years assigned. 2.5.42.74. Character in Register Book.

Present Condition of the Decks Good Good Good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Wales do Rudder do
 Plank (Bottom) and Counter do Copper or Y.M. ✓ When put on ✓
 Engine Room Skylights do Caulking of Bottom, Deck, & Waterways do
 Coal Bunker, Openings, Lids, &c. do Scuppers do
 General Observations, Opinion as to Class, &c. do Cargo and Main Hatchways do Hatches do

Bottom cleaned and recoated. Rudder pintles pushed. Fore topmast, topgallant mast and one yard new.
This vessel appears eligible to remain as classed

Committee's Minute Friday, June, 25th 18 80
 Character assigned 100 A1 TBW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) ✓ Paid 18

No. 169 Survey held at London Date, first Survey 14 June Last Survey 14 June 1880
 No. in Reg. Book. 169 on the S. "Neva" Master Clark
 Tonnage 1109 Built at Glasgow When built 1864-5
 By whom built Laurie Owners Nourse
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Princes dry dock

Last Survey, No. 24867 Port of London Classed 100 A1 9.79
 Years assigned. 2.5.42.74. Character in Register Book.

Present Condition of the Decks Good Good Good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Wales do Rudder do
 Plank (Bottom) and Counter do Copper or Y.M. ✓ When put on ✓
 Engine Room Skylights do Caulking of Bottom, Deck, & Waterways do
 Coal Bunkers, Openings, Lids, &c. do Scuppers do
 General Observations, Opinion as to Class, &c. do Cargo and Main Hatchways do Hatches do

Bottom cleaned and recoated. Rudder pintles pushed. This vessel appears eligible to remain as classed.
Surveyed with outward cargo, coals, over the hold

Committee's Minute Friday, June, 25th 18 80
 Character assigned 100 A1 TBW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) ✓ Paid 18

Barossa
&
Neiva



© 2019

Lloyd's Register
Foundation