

ANNUAL SURVEYS.

26914

(Received at London Office,)

No. 25 Survey held at Middlebro' Date, first Survey 2nd June Last Survey 2nd June 1880
 No. in on the Iron Emmie Master J. Pratt
 Reg. Book. 120 Tonnage 130 Built at Middlebro' When built 1844
 By whom built Wraggs Owners Fordland & Stephen
 Port belonging to Middlebro' Destined Voyage France
 If Surveyed Afloat or in Dry Dock Slipway

694
16120

[Signature]

Last Survey, No. 24782 Port of London Classed 100 A 1
Years assigned. 10-19
 Present Condition of the Decks good Treenails good
 Waterways d^o Breasthooks and Stenson d^o
 Comings d^o Transoms, Pointers, and Crutches d^o
 Upper Deck Beams & Fastenings d^o Timbers of the Frame at the Openings d^o
 Lower Deck Beams & Fastenings d^o Ditto ditto at other places d^o
 Planksheers d^o Keelsons d^o
 Sheerstrakes d^o Clamps and Shelves d^o
 Topsides d^o Ceiling d^o
 Wales d^o Rudder d^o
 Plank (Bottom) and Counter d^o Copper or Y.M. Black Black When put on 1880
 Caulking of a Black Lead
 Bottom, Deck, & Waterways good
 Windlass and Capstan good
 Pumps d^o
 Boats d^o
 Masts, Yards, &c. d^o
 Condition, how ascertained d^o
 Sails d^o
 Anchors, No. of d^o
 Cables d^o
 Hawasers and Warps d^o
 Standing and Running Rigging d^o
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers good Cargo and Main Hatchways and Hatches good

General Observations, Opinion as to Class, &c.
This Schooner is in a good and efficient state of repair
fit for the safe conveyance of dry and perishable goods and
is eligible, in my opinion, to remain as classed

Committee's Minute Friday, July, 2nd 1880
 Character assigned 100 A 1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRM Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18
 No. in on the _____ Master _____
 Reg. Book. _____ Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
Years assigned. _____
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stenson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Caulking of _____
 Bottom, Deck, & Waterways _____
 Windlass and Capstan _____
 Pumps _____
 Boats _____
 Masts, Yards, &c. _____
 Condition, how ascertained _____
 Sails _____
 Anchors, No. of _____
 Cables _____
 Hawasers and Warps _____
 Standing and Running Rigging _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____

General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18

