

ANNUAL SURVEYS.

(Received at London Office, ...)

No. 14903 Survey held at Newcastle

Date, first Survey 19th June Last Survey 19th June 1880

No. in on the S. S. "Opere"

Master W. Kidney

Reg. Book.

931 Tonnage 554 Built at Newcastle

When built 1878 5th Mo

By whom built Mitchell

Owners R. B. Furwick & J. Reed

Port belonging to Newcastle

Destined Voyage Stettin

1 Surveyed Afloat or in Dry Dock on the Walland Ship

Last Survey, No. 25347

Port of pm

Classed

Years assigned.

Character in Register Book.

90A1

12.79

Present Condition of the

Decks

Good

Timber Rich-

Good

Waterways

Breasthooks and Stemson

Windlass and Capstan

Comings

Transoms, Pointers, and Crutches

Pumps

Upper Deck Beams & Fastenings

Timbers of the Frame at the Openings

Boats

Lower Deck Beams & Fastenings

Ditto ditto at other places

Masts, Yards, &c.

Planksheers

Keelsons

Condition, how ascertained On Deck

Sheerstrakes

Clamps and Shelves

Sails Sufficient

Topsides

Ceiling

Anchors, No. of 3 B. 1 S. 2 R

Wales

Rudder

Cables Complete

Plank (Bottom) and Counter

Copper or Y.M. Paint When put on on

Hawsers and Warps Sufficient

Engine Room Skylights

Good

Coal Bunker, Openings, Lids, &c.

Good

Scuppers

Good

Cargo and Main Hatchways

Good

Hatches

Good

General Observations, Opinion as to Class, &c.

The Bottom of this vessel has been cleaned & scraped, she is appearing in good condition & eligible in my opinion to remain as classed.

Committee's Minute

Friday, July, 2nd 1880

Character assigned

90A1

TBW

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) — Paid — 18 —

No.

Survey held at South Shields

Date, first Survey 21st June Last Survey 2nd June 1880

No. in on the S. S. "Brooklyn"

Master J. Burrie

Reg. Book.

1049 Tonnage 789 Built at W. Hartlepool

When built 1876 12th Mo

By whom built Gray

Owners J. Murgmatten & Co

Port belonging to W. Hartlepool

Destined Voyage Brussels

1 Surveyed Afloat or in Dry Dock Edwards High Dock.

Last Survey, No. 23402

Port of pm

Classed

Years assigned.

Character in Register Book.

100A1

7.79

Present Condition of the

Decks

Good

Timber Rich-

Good

Waterways

Breasthooks and Stemson

Windlass and Capstan

Comings

Transoms, Pointers, and Crutches

Pumps

Upper Deck Beams & Fastenings

Timbers of the Frame at the Openings

Boats

Lower Deck Beams & Fastenings

Ditto ditto at other places

Masts, Yards, &c.

Planksheers

Keelsons

Condition, how ascertained On Deck

Sheerstrakes

Clamps and Shelves

Sails Sufficient

Topsides

Ceiling

Anchors, No. of 3 B. 1 S. 2 R

Wales

Rudder

Cables Complete

Plank (Bottom) and Counter

Copper or Y.M. Paint When put on on

Hawsers and Warps Sufficient

Engine Room Skylights

Good

Coal Bunkers, Openings, Lids, &c.

Good

Scuppers

Good

Cargo and Main Hatchways

Good

Hatches

Good

General Observations, Opinion as to Class, &c.

The Bottom of this vessel has been cleaned & scraped, she is appearing in good condition & eligible in my opinion to remain as classed.

Committee's Minute

Friday, July, 2nd 1880

Character assigned

100A1

TBW

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) — Paid — 18 —