

ANNUAL SURVEYS.

26995

(Received at London Office, 3.7.80)

No. 39254 Survey held at London Date, first Survey 19th June Last Survey 22nd June 1880.
 No. in on the S. S. "Antonio" Master Seaborne
 Reg. Book. 1082 Tonnage 1214 1858/174 Built at Sunderland When built 1877 6th mo.
 By whom built Doxford Owners Steam Nav. Co. Nord (lim)
 Port belonging to London Destined Voyage Cronstadt
 If Surveyed Afloat X in Dry Dock Millwall Graving Dock

Last Survey, No. 26752 Port of Iron Classified 100 A1
 Years assigned. 1.80 Character in Register Book.

Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do Windlass and Capstan Good
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do Pumps do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do Boats 4 in number do
 Planksheers do Keelsons do Masts, Yards, &c. do
 Sheerstrakes do Clamps and Shelves do Condition, how ascertained from Deck & enquiry
 Topsides do Ceiling do Sails do
 Wales do Rudder do Anchors, No. of 3 B. 1 St. 2 H. do
 Plank (Bottom) and Counter do Copper or Y.M. Paint When put on now Cables part seen do
 Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers do Hawesers and Warps do
 General Observations, Opinion as to Class, &c. Standing and Running Rigging do
Cargo and Main Hatchways good Hatches do

Several rivets in afterend of keel renewed.
Bottom repainted.

She is in good condition & eligible in my opinion to remain as classed.

Committee's Minute Tuesday, July, 6th 1880

Character assigned 100 A1
Subject to the Exam. & P. in Six Months

W. Taulsen
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classified
 Years assigned. Character in Register Book.

Present Condition of the
 Decks Treenails Breasthooks and Stemson Windlass and Capstan
 Waterways Transoms, Pointers, and Crutches Pumps
 Comings Timbers of the Frame at the Openings Boats
 Upper Deck Beams & Fastenings Ditto ditto at other places Masts, Yards, &c.
 Lower Deck Beams & Fastenings Keelsons Condition, how ascertained
 Planksheers Clamps and Shelves Sails
 Sheerstrakes Ceiling Anchors, No. of
 Topsides Rudder Cables
 Wales Copper or Y.M. When put on Hawesers and Warps
 Plank (Bottom) and Counter Caulking of Standing and Running Rigging
 Engine Room Skylights Bottom, Deck, & Waterways Cargo and Main Hatchways Hatches
 Coal Bunkers, Openings, Lids, &c. Scuppers
 General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18