

ANNUAL SURVEYS. 27/11/8

No. 177. Survey held at Bordeaux Date, first Survey 7th July Last Survey 7 July 1880
No. in on the iron B.K. Elliot Master W. A. Mackay
Reg. Book. Tonnage 1119 Built at Aberdeen When built 1877. 4 months.
560 By whom built A. Hall & Co. Owners J. Muir -
547 Port belonging to Arbroth Destined Voyage New port. England
If Surveyed Afloat or in Dry Dock on the Ship

Last Survey, No. 2105 Port of London Iron
Present Condition of the
Decks Good Treenails rivets in good order.
Waterways d^o Breasthooks and Stemson
Comings d^o Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings $\frac{1}{2}$ Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings $\frac{1}{2}$ Ditto ditto at other places
Planksheers Good Keelsons
Sheerstrakes Good Clamps and Shelves
Topsides d^o Ceiling
Wales d^o Rudder repaired & Good
Plank (Bottom) and Counter d^o Copper or Y.M. When put on
Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers
General Observations, Opinion as to Class, &c. Cargo and Main Hatchways Hatches

Windlass and Capstan Good
Pumps d^o
Boats 6 d^o
Masts, Yards, &c. $\frac{1}{2}$
Condition, how ascertained $\frac{1}{2}$
Sails $\frac{1}{2}$
Anchors, No. of Complete
Cables
Hawsers and Warps
Standing and Running Rigging good.

Bottom examined on a Slip - Scraped and painted. So far as examined, this vessel was found in very good condition and eligible in my opinion to remain as classed 100 A.I.

Committee's Minute Tuesday, July, 13th 18

Character assigned 100 A.I.

Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid £0.5.0 18 80

No. Survey held at Date, first Survey Last Survey 18
No. in on the Master
Reg. Book. Tonnage Built at When built
By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
Present Condition of the
Decks Treenails
Waterways Breasthooks and Stemson
Comings Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings Ditto ditto at other places
Planksheers Keelsons
Sheerstrakes Clamps and Shelves
Topsides Ceiling
Wales Rudder
Plank (Bottom) and Counter Copper or Y.M. When put on
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers
General Observations, Opinion as to Class, &c. Cargo and Main Hatchways Hatches

Windlass and Capstan
Pumps
Boats
Masts, Yards, &c.
Condition, how ascertained
Sails
Anchors, No. of
Cables
Hawsers and Warps
Standing and Running Rigging

Committee's Minute 18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18