

ANNUAL SURVEYS.

27141

No. 29381 Survey held at London Date, first Survey 24th June Last Survey 24th June 1880
 No. in on the S. S. "Lisbon" Master J. L. Hall
 Reg. Book. 495 Tonnage 860 1334 1294 Built at W. Hartlepool When built 1871 4th mo.
 By whom built Denton Owners J. Hall jun & Co.
 Port belonging to London Destined Voyage Lisbon & Cadiz
 If Surveyed Afloat or in Dry Dock Union Dry Dock


Last Survey, No. 25335 Port of Iron Classed 100 A1
 Present Condition of the Decks Good Treennails Good Rivets Good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Wales do Rudder do
 Plank (Bottom) and Counter do Copper or Y.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers do Cargo and Main Hatchways good Hatches do
 General Observations, Opinion as to Class, &c. Rudder pintles bushed. - Bottom repainted. -

She is now in good condition & eligible in my opinion to remain as classed.
 Committee's Minute Tuesday, July, 13th 1880.
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) DTB Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

I Survey, No. Port of Classed
 Present Condition of the Decks Treennails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18



1873

Last Survey, No.		Port of		Classed	
1		Lisbon		1	
2		Lisbon		2	
3		Lisbon		3	
4		Lisbon		4	
5		Lisbon		5	
6		Lisbon		6	
7		Lisbon		7	
8		Lisbon		8	
9		Lisbon		9	
10		Lisbon		10	
11		Lisbon		11	
12		Lisbon		12	
13		Lisbon		13	
14		Lisbon		14	
15		Lisbon		15	
16		Lisbon		16	
17		Lisbon		17	
18		Lisbon		18	
19		Lisbon		19	
20		Lisbon		20	
21		Lisbon		21	
22		Lisbon		22	
23		Lisbon		23	
24		Lisbon		24	
25		Lisbon		25	
26		Lisbon		26	
27		Lisbon		27	
28		Lisbon		28	
29		Lisbon		29	
30		Lisbon		30	
31		Lisbon		31	
32		Lisbon		32	
33		Lisbon		33	
34		Lisbon		34	
35		Lisbon		35	
36		Lisbon		36	
37		Lisbon		37	
38		Lisbon		38	
39		Lisbon		39	
40		Lisbon		40	
41		Lisbon		41	
42		Lisbon		42	
43		Lisbon		43	
44		Lisbon		44	
45		Lisbon		45	
46		Lisbon		46	
47		Lisbon		47	
48		Lisbon		48	
49		Lisbon		49	
50		Lisbon		50	
51		Lisbon		51	
52		Lisbon		52	
53		Lisbon		53	
54		Lisbon		54	
55		Lisbon		55	
56		Lisbon		56	
57		Lisbon		57	
58		Lisbon		58	
59		Lisbon		59	
60		Lisbon		60	
61		Lisbon		61	
62		Lisbon		62	
63		Lisbon		63	
64		Lisbon		64	
65		Lisbon		65	
66		Lisbon		66	
67		Lisbon		67	
68		Lisbon		68	
69		Lisbon		69	
70		Lisbon		70	
71		Lisbon		71	
72		Lisbon		72	
73		Lisbon		73	
74		Lisbon		74	
75		Lisbon		75	
76		Lisbon		76	
77		Lisbon		77	
78		Lisbon		78	
79		Lisbon		79	
80		Lisbon		80	
81		Lisbon		81	
82		Lisbon		82	
83		Lisbon		83	
84		Lisbon		84	
85		Lisbon		85	
86		Lisbon		86	
87		Lisbon		87	
88		Lisbon		88	
89		Lisbon		89	
90		Lisbon		90	
91		Lisbon		91	
92		Lisbon		92	
93		Lisbon		93	
94		Lisbon		94	
95		Lisbon		95	
96		Lisbon		96	
97		Lisbon		97	
98		Lisbon		98	
99		Lisbon		99	
100		Lisbon		100	

