

ANNUAL SURVEYS.

No. 2360 Survey held at London Date, first Survey 30th June Last Survey 6th July 18 80
 No. in on the Ship "Opawa" Master Friston
 Reg. Book. 196 Tonnage 1076 1131 980 Built at Glasgow When built 1876 11th mo.
 By whom built Stephen Owners New Zealand Shipp. Co. (lim.)
 Port belonging to London Destined Voyage New Zealand
 If Surveyed Afloat X in Dry Dock Canal Dry Dock

Last Survey, No. 23993 Port of Iron Classed 100 A1
 Present Condition of the Decks Good Treenails Rivets Good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Wales do Rudder do
 Plank (Bottom) and Counter do Copper or F.M. Paint When put on now
 Engine Room Skylights — Caulking of Bottom, Deck, & Waterways good
 Coal Bunker, Openings, Lids, &c. good Scuppers do Cargo and Main Hatchways good Hatches do
 General Observations, Opinion as to Class, &c.

Several rivets in upper deck beam arms renewed.

Bottom cleaned & repainted.

Surveyed with ballast & part outward cargo in hold fore & aft.
She is in good condition & eligible in my opinion to remain as classed.
 Committee's Minute Friday, July, 9th 18 80

Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

No. 24317 Survey held at London Date, first Survey 5th July Last Survey 7th July 18 80
 No. in on the Ship "Wanganui" Master H. Watt
 Reg. Book. 70 Tonnage 1077 1136 984 Built at Glasgow When built 1877 1st mo.
 By whom built Stephen Owners New Zealand Ship. Co. (lim.)
 Port belonging to London Destined Voyage Auckland
 If Surveyed Afloat X in Dry Dock Canal Dry Dock

Last Survey, No. 24317 Port of Iron Classed 100 A1
 Present Condition of the Decks Good Treenails Rivets Good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Wales do Rudder do
 Plank (Bottom) and Counter do Copper or F.M. Paint When put on now
 Engine Room Skylights — Caulking of Bottom, Deck, & Waterways good
 Coal Bunkers, Openings, Lids, &c. — Scuppers do Cargo and Main Hatchways good Hatches do
 General Observations, Opinion as to Class, &c.

Bottom cleaned & repainted.

Surveyed with ballast in hold all fore & aft.

She is in good condition & eligible in my opinion to remain as classed.
 Committee's Minute Friday, July, 9th 18 80

Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

Ofona
Wanganui

