

ANNUAL SURVEYS.

No. 29373 Survey held at London Date, first Survey 30th June Last Survey 30th June 1880
 No. in on the Ship "Myra" Master R. Jamieson
 Reg. Book. 796 Tonnage 130.5 137.2 118.5 Built at Aberdeen When built 1876 10th
 By whom built Hood Owners G. Thompson & Co.
 Port belonging to Aberdeen Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Canal Dry Dock.
 Last Survey, No. 24180 Port of Prov. Classed 100 A1
 Years assigned. 7. 49 Character in Register Book.

Present Condition of the Decks	<u>Good</u>	<u>Treenails</u>	<u>Rivets</u>	<u>Good</u>
Waterways	<u>do</u>	Breasthooks and Stemson		<u>do</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches		<u>do</u>
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings		<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places		<u>do</u>
Planksheers	<u>do</u>	Keelsons		<u>do</u>
Sheerstrakes	<u>do</u>	Clamps and Shelves		
Topsides	<u>do</u>	Ceiling		<u>do</u>
Wales	<u>do</u>	Rudder		<u>do</u>
Plank (Bottom) and Counter	<u>do</u>	Copper or Y.M. Paint When put on <u>see</u>		
Engine Room Skylights	<u>—</u>	Caulking of Bottom, Deck, & Waterways	<u>good</u>	
Coal Bunker, Openings, Lids, &c.	<u>—</u>	Scuppers	<u>do</u>	
General Observations, Opinion as to Class, &c.				

Windlass and Capstan Good
 Pumps do
 Boats 5 in number do
 Masts, Yards, &c. do
 Condition, how ascertained from DR & Enquiry
 Sails do
 Anchors, No. of 3 B. 1st. 2 1/2. do
 Cables ft. seen do
 Hawser and Warps do
 Standing and Running Rigging do
 Cargo and Main Hatchways good Hatches do

Bottom cleaned & repainted.
Surveyed with part outward cargo in hold all fore & aft.
She is in good condition & eligible in my opinion to remain as classed.
 Committee's Minute Friday, July, 9th, 1880
 Character assigned 100 A1
W. Taulsen.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid — 18—

No. — Survey held at — Date, first Survey — Last Survey — 18—
 No. in on the — Master —
 Reg. Book. — Tonnage — Built at — When built —
 By whom built — Owners —
 Port belonging to — Destined Voyage —
 If Surveyed Afloat or in Dry Dock —

Last Survey, No. — Port of — Classed —
 Years assigned. — Character in Register Book.
 Present Condition of the Decks —
 Waterways — Treenails —
 Comings — Breasthooks and Stemson —
 Upper Deck Beams & Fastenings — Transoms, Pointers, and Crutches —
 Lower Deck Beams & Fastenings — Timbers of the Frame at the Openings —
 Planksheers — Ditto ditto at other places —
 Sheerstrakes — Keelsons —
 Topsides — Clamps and Shelves —
 Wales — Ceiling —
 Plank (Bottom) and Counter — Rudder —
 Engine Room Skylights — Copper or Y.M. When put on —
 Coal Bunkers, Openings, Lids, &c. — Caulking of Bottom, Deck, & Waterways —
 Scuppers — Cargo and Main Hatchways — Hatches —
 General Observations, Opinion as to Class, &c. —

Committee's Minute — 18—
 Character assigned —
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid — 18—

Myra

ANNUAL SURVEYS

Last Survey, No.		Part of		Class	
1		1		1	
2		2		2	
3		3		3	
4		4		4	
5		5		5	
6		6		6	
7		7		7	
8		8		8	
9		9		9	
10		10		10	
11		11		11	
12		12		12	
13		13		13	
14		14		14	
15		15		15	
16		16		16	
17		17		17	
18		18		18	
19		19		19	
20		20		20	
21		21		21	
22		22		22	
23		23		23	
24		24		24	
25		25		25	
26		26		26	
27		27		27	
28		28		28	
29		29		29	
30		30		30	
31		31		31	
32		32		32	
33		33		33	
34		34		34	
35		35		35	
36		36		36	
37		37		37	
38		38		38	
39		39		39	
40		40		40	
41		41		41	
42		42		42	
43		43		43	
44		44		44	
45		45		45	
46		46		46	
47		47		47	
48		48		48	
49		49		49	
50		50		50	
51		51		51	
52		52		52	
53		53		53	
54		54		54	
55		55		55	
56		56		56	
57		57		57	
58		58		58	
59		59		59	
60		60		60	
61		61		61	
62		62		62	
63		63		63	
64		64		64	
65		65		65	
66		66		66	
67		67		67	
68		68		68	
69		69		69	
70		70		70	
71		71		71	
72		72		72	
73		73		73	
74		74		74	
75		75		75	
76		76		76	
77		77		77	
78		78		78	
79		79		79	
80		80		80	
81		81		81	
82		82		82	
83		83		83	
84		84		84	
85		85		85	
86		86		86	
87		87		87	
88		88		88	
89		89		89	
90		90		90	
91		91		91	
92		92		92	
93		93		93	
94		94		94	
95		95		95	
96		96		96	
97		97		97	
98		98		98	
99		99		99	
100		100		100	