

ANNUAL SURVEYS.

27225

No. 358 Survey held at Hamburg Date, first Survey 13th May Last Survey 18th May 1880
 No. in on the S. S. Germania Master E. Weitschewsky
 Reg. Book. 275 Tonnage 433 Built at Sunderland When built 1856
273 By whom built Laing Owners H. J. Perlbach & Co.
 Port belonging to Hamburg Destined Voyage _____
 If Surveyed Afloat or in Dry Dock On patent slip

Last Survey, No. 2021 Port of Iron Classed 8078 A-
Years assigned. Character in Register Book.

Present Condition of the Decks <u>Good</u>	Treenails <u>Riveting</u> <u>Good</u>	
Waterways <u>do</u>	Breasthooks and Stemson _____	<u>2,78.</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches _____	<u>s. s. Ham. No. 2-78.</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the Openings _____	Windlass and Capstan <u>Good</u>
Lower Deck Beams & Fastenings <u>do</u>	Ditto ditto at other places _____	Pumps <u>do</u>
Planksheers _____	Keelsons _____ <u>do</u>	Boats <u>do</u>
Sheerstrakes _____	Clamps and Shelves _____	Masts, Yards, &c. <u>do</u>
Topsides _____	Ceiling _____ <u>do</u>	Condition, how ascertained _____
Wales _____	Rudder _____ <u>do</u>	Sails <u>do</u>
Plank (Bottom) and Counter <u>Good</u>	Copper or Y.M. <u>Painted</u> When put on <u>Now</u>	Anchors, No. of <u>Six</u> <u>do</u>
Engine Room Skylights <u>Good</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	Cables _____ <u>do</u>
Coal Bunker, Openings, Lids, &c. <u>Good</u>	Scuppers <u>Good</u>	Hawsers and Warps _____ <u>do</u>
General Observations, Opinion as to Class, &c.	Cargo and Main Hatchways <u>Good</u>	Standing and Running Rigging _____ <u>do</u>
	Hatches <u>Good</u>	

Ship placed on patent slip, bottom examined and found in very good condition. The cement also examined in some parts and found very good.
 She is in good condition and, in my opinion, has to remain in her character.

Committee's Minute Friday, July, 2nd 1880
 Character assigned 80 A-
Lloyd's No. 5, 80
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 5/ Paid 28/6 1880

No. _____ Survey held at 12 Months Date, first Survey do Last Survey 7/4/80 1880
 No. in on the _____ Master _____
 Reg. Book. _____ Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
Years assigned. Character in Register Book.

Present Condition of the Decks _____	Treenails _____	
Waterways _____	Breasthooks and Stemson _____	Windlass and Capstan _____
Comings _____	Transoms, Pointers, and Crutches _____	Pumps _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Boats _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Masts, Yards, &c. _____
Planksheers _____	Keelsons _____	Condition, how ascertained _____
Sheerstrakes _____	Clamps and Shelves _____	Sails _____
Topsides _____	Ceiling _____	Anchors, No. of _____
Wales _____	Rudder _____	Cables _____
Plank (Bottom) and Counter _____	Copper or Y.M. _____ When put on _____	Hawsers and Warps _____
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways _____	Standing and Running Rigging _____
Coal Bunkers, Openings, Lids, &c. _____	Scuppers _____	Cargo and Main Hatchways _____
General Observations, Opinion as to Class, &c.	Hatches _____	

Committee's Minute _____ 18 _____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____



1206493-0533