

REPORT of SURVEY for REPAIRS, &c.

27239

(Received at London Office, 14 June 1880)

No. in Survey held at London Date, first Survey 21 May Last Survey 4 June 1880
 g. Book. 599 on the 10th "Poulin Castle" Master George Anderson
 TONNAGE under Tonnage Deck 635 Built at Glasgow When built 1863
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage 644 Owners Skinner & Co Port belonging to Glasgow
 Crew Space, as per Rule
 Register Tonnage, cut on Beam 644 Residence
 Engine Room By whom built Cannell Destined Voyage Adelaide via Middlehead
 Reg. Tons as St' mer, cut on Bm. If Surveyed Afloat or in Dry Dock Princes dry dock
(State Name of Dock)

Length of Poop _____ ft. Ditto, Forecastle _____ ft. Ditto, Raised Quarter Deck _____ ft. Years assigned. _____ Character in Register Book. _____
 Last Survey, No. 26534 Port Iron Classed 4/7 1 11 77
 REPAIRS, OR EXAMINATION AS PER RULE R.P. 43.77.
 Cause of Repairs to be clearly stated.

The main bulwarks renewed from raised quarter deck forward to monkey fore-castle with 76 plate.
 Three pintles of rudder renewed.
 Bottom cleaned and recoated - bathears new.
 Fibboom renewed.

Power Anchor supplied. ^{cut in the June} 20.3.14 test 21.10.17. 14 Jan 1879.
 Certificate produced and signed by J. Hartness.

Present Condition of the	Good	Freenails	Quets	Good	Windlass and Capstan	Good	
Decks	de	Breasthooks and Stenson	de	de	Pumps	de	
Waterways	de	Transoms, Pointers, and Crutches	de	de	Boats	de	
Comings	de	Timbers of the Frame at the openings	de	de	Masts, Yards, &c.	de	
Upper Deck Beams & Fastenings	de	Ditto Ditto at other places	de	de	Condition, how ascertained from deck	de	
Lower Deck Beams & Fastenings	de	Keelsons	de	de	Sails	well found	
Planksheers	de	Clamps and Shelves	de	de	Anchors	No. of 3 B. 1 S. 2 Wedges	
Sheerstrakes	de	Ceiling	de	de	Cables	Complete	
Topsides	de	Rudder	de	de	Hawsers and Warps	Sufficient	
Wales	de	Copper (or Y.M.)	✓	When put on	✓	Standing & Running Rigging	good
Plank (Bottom) and Counter	de	Caulking of				Cargo and Main Hatchways	de
Engine Room Skylights		Bottom, Deck, & Waterways				Hatches	de
Coal Bunker, Openings, Lids, &c.							
Scuppers	de						

General Observations, Opinion as to Class, &c.
 This vessel appears in good condition and eligible to remain as classed.

The Amount of Entry Fee ... £ 14/6/0 Special ... £ 2 : 2 : 10/6 1880 received by me, J.M. Ho. Bougdon
 Certificate (if required) to be sent as per margin... } £ - : 5 : -
 Surveyor to Lloyd's Register of British and Foreign Shipping

(Travelling Expenses, if any, £ _____)
 Committee's Minute Tuesday, June 15th 1880.
 Character assigned JTBW



Roden Castle



© 2019

Lloyd's Register
Foundation