

ANNUAL SURVEYS.

Recd 30.6.80

No. in Reg. Book. on the No. 393110 Survey held at London Date, first Survey May 28th Last Survey June 26th 1880
1052 Tonnage 955 Built at Belfast When built 1864
 By whom built Harland Owners J. Long & Co
 Port belonging to Belfast Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Green's Dry Dock & Afloat
 Last Survey, No. N 393110 Port of Iron Classed A 1 4-80.
 Years assigned. Character in Register Book.

Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Copper When put on non
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom & copper

She is now in good condition and eligible to remain as classed

Committee's Minute

Friday, July, 2nd 18 80

Character assigned

A 1

DBW

Senhouse Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. in Reg. Book. on the No. 393110 Survey held at London Date, first Survey May 15 Last Survey June 21st 1880
163 Tonnage 1837 Built at Aberdeen When built 1867
 By whom built Hard Owners J. Thompson & Co
 Port belonging to Aberdeen Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Green's Dry Dock & Afloat
 Last Survey, No. 20860 Port of Iron Classed A 1 4-78.
 Years assigned. Character in Register Book.

Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Copper When put on non
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom & copper

She is now in good condition and eligible to remain as classed.

Committee's Minute

Friday, July, 2nd 18 80

Character assigned

A 1

DBW

Senhouse Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

120N493-0558

Handwritten notes in the top left corner, possibly "List of ..."

ANNUAL SURVEYS



© 2019

Lloyd's Register
Foundation