

ANNUAL SURVEYS.

27279

No. 29421 Survey held at London Date, first Survey June 18th Last Survey July 6th 1880
 in on the SS Dublin Castle Master _____
 No. in on the SS Dublin Castle Master _____
 Tonnage 1856 Built at Glasgow When built 1877-5M
 By whom built Napier Owners J Currie & Co
 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 26085 Port of Iron Classed 100A-3-80
 Present Condition of the _____

<u>Good</u> Treennails	<u>Rivets</u>	<u>Good</u>
Waterways	Breasthooks and Stemson	Windlass and Capstan <u>Good</u>
Platings	Transoms, Pointers, and Crutches	Pumps
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Boats
Lower Deck Beams & Fastenings	Ditto ditto at other places	Masts, Yards, &c.
Planksheers	Keelsons	Condition, how ascertained <u>From St</u>
Deerstrakes	Clamps and Shelves	Sails <u>Good</u>
Sides	Ceiling	Anchors, No. of <u>3 Bes. St & Redgs</u>
Decks	Rudder	Cables <u>Part on St</u>
Plank (Bottom) and Counter	Copper or Y.M. <u>Coated</u> When put on <u>new</u>	Hawsers and Warps
Engine Room Skylights <u>Good</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	Standing and Running Rigging
Coal Bunker, Openings, Lids, &c. <u>Good</u>	Scuppers <u>Good</u>	Cargo and Main Hatchways <u>Good</u>
Hatches		

General Observations, Opinion as to Class, &c. Bottom to be coated.
She is now in good condition and eligible to remain as classed.

Committee's Minute Tuesday, July, 27th. 1880.
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping. Senhouse Mustindale
 Certificate (if required) _____ Paid _____ 18____

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 in on the _____ Master _____
 No. in on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
 Present Condition of the _____

Treennails		
Waterways	Breasthooks and Stemson	Windlass and Capstan
Platings	Transoms, Pointers, and Crutches	Pumps
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Boats
Lower Deck Beams & Fastenings	Ditto ditto at other places	Masts, Yards, &c.
Planksheers	Keelsons	Condition, how ascertained
Deerstrakes	Clamps and Shelves	Sails
Sides	Ceiling	Anchors, No. of
Decks	Rudder	Cables
Plank (Bottom) and Counter	Copper or Y.M. _____ When put on _____	Hawsers and Warps
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways	Standing and Running Rigging
Coal Bunkers, Openings, Lids, &c.	Scuppers	Cargo and Main Hatchways
Hatches		

General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping. _____
 Certificate (if required) _____ Paid _____ 18____

