

ANNUAL SURVEYS.

27311

No. 29424 Survey held at London Date, first Survey 3rd June Last Survey 15th July 1880
No. in on the Iron S.S. "Mantua" Master L. Lobling
Reg. Book. 543 Tonnage 617.959.74 Built at Newcastle When built 1875. 5mo
By whom built Mitchell Owners Gen Steam Nav Co
Port belonging to London Destined Voyage Hamburg
If Surveyed Afloat or in Dry Dock Deptford Green dry dock & afloat

Last Survey, No. 23884 Port of Iron Classed 100A 15.79
Present Condition of the Decks Good Treenails Good Breasthooks and Stemson Good
Waterways Good Transoms, Pointers, and Crutches Good Windlass and Capstan Good
Comings Good Timbers of the Frame at the Openings Good Pumps Good
Upper Deck Beams & Fastenings Good Ditto ditto at other places Good Boats 4th
Lower Deck Beams & Fastenings Good Keelsons Good Masts, Yards, &c. Good
Planksheers Good Clamps and Shelves Good Condition, how ascertained from deck
Sheerstrakes Good Ceiling Good Sails Good
Topsides Good Rudder Good Anchors, No. of Good
Wales Good Copper or Y.M. Cement When put on 1875 Cables 240 fms
Plank (Bottom) and Counter Good Caulking of Bottom, Deck, & Waterways Good Hawseers and Warps Good
Standing and Running Rigging Good
Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. Bottom renovated. cables raised out and deficiency supplied with 30 fms 1 1/2" No 6307 Leads 40 1/2 tons & 58 1/4". Rebuilt on Public machine 18th June 1880 D.G. Lewis Supd. She is now in good condition and eligible in my opinion to continue as classed

Committee's Minute

Friday, July, 30th 18 80

Character assigned

100A 1

W. L. Lacey
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18

No. Survey held at Date, first Survey Last Survey 18
No. in on the Master
Reg. Book. Tonnage Built at When built
By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
Present Condition of the Decks
Waterways
Comings
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Planksheers
Sheerstrakes
Topsides
Wales
Plank (Bottom) and Counter
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18