

6/8/80

ANNUAL SURVEYS.

27342

No. 39473 Survey held at London Date, first Survey July 24 Last Survey Aug 11 1880
 No. in on the S Star of Erin Master J Boulton
 Reg. Book. 117 Tonnage 949 Built at Belfast When built 1862
 By whom built Harland Owners J Barry & Co
 Port belonging to Belfast Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 24077 Port of Iron
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " ~~Copper or V.M. Coated~~ When put on new
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom &c Coated

Classed A1 7-77.
 SS San Mateo

Committee's Minute Tuesday, August 10th. 1880.
 Character assigned 10.8.80
Senhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

No. 417 Survey held at London Date, first Survey June 24 Last Survey July 13 1880
 No. in on the S Rajpoot Master J Anderson
 Reg. Book. 117 Tonnage 1244 Built at Liverpool When built 1864-7
 By whom built Vernon Owners J K Welch
 Port belonging to London Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 24084 Port of Iron
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " ~~Copper or V.M. Coated~~ When put on new
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom &c Coated

Classed A1 7-77.
 SS San Mateo

Committee's Minute Tuesday, August 10th. 1880.
 Character assigned 10.8.80
Senhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18