

ANNUAL SURVEYS.

(Received at London Office, 22.7.80)

No. 39439 Survey held at London Date, first Survey June 28<sup>th</sup> Last Survey July 19<sup>th</sup> 1880  
No. in on the SS Dunrobin Castle Master Horvson  
Reg. Book. 1784 Tonnage 2811 Built at Glasgow When built 1875 11 mo.  
548 By whom built Napier Owners S Currie & Co  
Port belonging to London Destined Voyage Cape  
If Surveyed Afloat or in Dry Dock Thames Iron Works Dry Dock  
Last Survey, No. 24669 Port of Iron. Classed 100 A1 2.73

Present Condition of the  
Decks Good Treenails Rivets Good  
Waterways " Breasthooks and Stemson " " "  
Comings " Transoms, Pointers, and Crutches " "  
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " "  
Lower Deck Beams & Fastenings " Ditto ditto at other places " "  
Planksheers " Keelsons " "  
Sheerstrakes " Clamps and Shelves " "  
Topsides " Ceiling " "  
Wales " Rudder " "  
Plank (Bottom) and Counter " Copper or Y.M. Boutue When put on none  
Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "  
General Observations, Opinion as to Class, &c. Bottom & counter, Chain cables ranged for Government  
Surveyors & examined by me 300 fathoms, she is in good condition  
and eligible to remain as classed  
She was specially surveyed for S.S.M. three months  
since

Committee's Minute Friday, July, 30th 1880  
Character assigned 100 A1  
Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required) Paid 18

No. Survey held at Date, first Survey Last Survey 18  
No. in on the Master  
Reg. Book. Tonnage Built at When built  
By whom built Owners  
Port belonging to Destined Voyage  
If Surveyed Afloat or in Dry Dock  
Last Survey, No. Port of Classed

Present Condition of the  
Decks Treenails  
Waterways Breasthooks and Stemson  
Comings Transoms, Pointers, and Crutches  
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings  
Lower Deck Beams & Fastenings Ditto ditto at other places  
Planksheers Keelsons  
Sheerstrakes Clamps and Shelves  
Topsides Ceiling  
Wales Rudder  
Plank (Bottom) and Counter Copper or Y.M. When put on  
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches  
General Observations, Opinion as to Class, &c.

Committee's Minute 18  
Character assigned  
Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required) Paid 18

IRON 494-0127