

## ANNUAL SURVEYS.

27388

No. 2470 Survey held at London Date, first Survey July 21<sup>st</sup> Last Survey Aug 2<sup>d</sup> 1880  
 No. in on the SS Glenarthy Master H. Smith  
 Reg. Book. 1400 Tonnage 2143 Built at Glasgow When built 1873-9  
431 By whom built London & Glasgow Co Owners Mr Gregor Gow & Co  
 Port belonging to Glasgow Destined Voyage China  
 If Surveyed Afloat or in Dry Dock Queens Dry Dock

Last Survey, No. 25954Port of Iron

Classed

Years assigned.

Character in Register Book.

100 A1 1880SS Iron No 1-78.

Present Condition of the

Decks GoodTreenails Rivets GoodWaterways "Breasthooks and Stemson "Comings "Transoms, Pointers, and Crutches "Upper Deck Beams & Fastenings "Timbers of the Frame at the Openings "Lower Deck Beams & Fastenings "Ditto ditto at other places "Planksheers "Keelsons "Sheerstrakes "Clamps and Shelves "Topsides "Ceiling "Plank (Bottom) and Counter "Rudder "Copper or Y.M. Copper When put on nowCaulking of GoodBottom, Deck, & Waterways GoodEngine Room Skylights GoodCoal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "General Observations, Opinion as to Class, &c. Bottom be coated

*She is now in good condition  
and eligible to remain as classed.*

Committee's Minute

Tuesday, August 10th. 1880.

Character assigned

Senhouse Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) 18

No. Survey held at Date, first Survey Last Survey 18

No. in on the Master

Reg. Book. Tonnage Built at When built

By whom built Owners

Port belonging to Destined Voyage

If Surveyed Afloat or in Dry Dock

Last Survey, No.

Port of

Classed

Years assigned.

Character in Register Book.

Present Condition of the

Decks

Treenails

Waterways

Breasthooks and Stemson

Comings

Transoms, Pointers, and Crutches

Upper Deck Beams &amp; Fastenings

Timbers of the Frame at the Openings

Lower Deck Beams &amp; Fastenings

Ditto ditto at other places

Planksheers

Keelsons

Sheerstrakes

Clamps and Shelves

Topsides

Ceiling

Wales

Rudder

Plank (Bottom) and Counter

Copper or Y.M. When put on

Caulking of

Bottom, Deck, &amp; Waterways

Engine Room Skylights

Coal Bunkers, Openings, Lids, &amp;c. Scuppers Cargo and Main Hatchways Hatches

General Observations, Opinion as to Class, &amp;c.

Committee's Minute 18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) 18