

Report of Survey for Repairs of Engines and Boilers.

To. 153
 No. in Survey held at Newport (Mon) Date, first Survey 30th June Last Survey 7th July 1880.
 g. Book. 204 on the Machinery of the M. Monger (Number of Visits 2)
 Name, Gross 634¹/₂ Built at L. Shields- When built 1875
 Ditto, Net 405⁻ Owners Dansey & Robinson Port belonging to London
 Diameter of Cylinder 23¹/₂ x 45⁻ Engines made by R. F. Marshall When made 1875
 Length of Stroke 30⁻ Boilers made by When made 1875
 Pressure of Steam 65⁻ h
 Registered Horse Power 85⁻ ☒ Surveyed Afloat on Dry Dock
 Last Survey No. 25339 Port Iron
 (Received at London Office, 26/7/80)
 Years assigned. 100 A
 Character in Register Book. 12, 74

Particulars of Repairs and Examination on account of condition of boiler.

Boiler lifted out of its seating. Lower circle of front of boiler riveted. 48 rivets cut out of bottom of shell in the two centre seams - and lower back circle recaulked. New piece of plate fitted to front of boiler near the port furnace for towing the feed valve. A few rivets renewed in each furnace. Five new Main stays fitted.

An additional safety valve fitted to downy boiler.

London Report N^o 25339 returned

ARK

General Observations, Opinion, and Recommendation:— The Machinery is now in good order and safe working condition, and in my opinion eligible to remain as classed, and to have a new machinery certificate granted.

Entry or Registering Fee ... £ :
 Survey Fee ... £ 2 : 2 : received by me, ARK
 Certificate (if required) ... £ : 19th July 1880

(Travelling Expenses, if any, £ — 15/-)

Committee's Minute
 26/7/80
 Assigned

Friday, August 6th. 1880

Shops. Pub. 12, 79 across
 TRW D.S. 7, 80

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

ARK
 Date 26/7/80

Lloyd's Register
 Foundation
 IRON494-0173

M. Monaco



© 2019

Lloyd's Register
Foundation