

ANNUAL SURVEYS.

No. 39457 Survey held at London Date, first Survey 26th July Last Survey 26th July 1880
 No. in on the Iron Sew. Sr. "Ossian." Master Jefferson
 Reg. Book. 309 Tonnage 1211 Built at Newcastle When built 1876-9 mo.
 By whom built Swan. Owners Glover Bros.
 Port belonging to London. Destined Voyage Not known.
 If Surveyed Afloat or in Dry Dock In Millwall Dry Dock.

Last Survey, No. 18214 Port of Iron

Classed

Years assigned.

Character in Register Book.

100 A.1.

4.77

Present Condition of the

Decks good
 Waterways D^o
 Comings D^o
 Upper Deck Beams & Fastenings D^o
 Lower Deck Beams & Fastenings D^o
 Planksheers D^o
 Sheerstrakes D^o
 Topsides D^o
 Wales D^o
 Plating D^o
 Plank (Bottom) and Counter D^o
 Treenails rivets good
 Breasthooks and Stemson D^o
 Transoms, Pointers, and Crutches D^o
 Timbers of the Frame at the Openings D^o
 Ditto ditto at other places D^o
 Keelsons D^o
 Clamps and Shelves D^o
 Ceiling D^o
 Rudder D^o
 Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways good

Windlass and Capstan D^o
 Pumps D^o
 Boats D^o
 Masts, Yards, &c. D^o
 Condition, how ascertained from the deck
 Sails good
 Anchors, No. of 3 B. 1 S. 2 K
 Cables complete
 Hawesers and Warps sufficient
 Standing and Running Rigging D^o

Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good.

General Observations, Opinion as to Class, &c.

The bottom has been examined, cleaned & coated. This vessel appears to be in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute

Friday, August 6th. 1880

Character assigned

100 A.1
 J.H.

J. H. Truscott.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

No. Survey held at Date, first Survey Last Survey 18

No. in on the Master
 Reg. Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No.

Port of

Classed

Years assigned.

Character in Register Book.

Present Condition of the

Decks
 Waterways
 Comings
 Upper Deck Beams & Fastenings
 Lower Deck Beams & Fastenings
 Planksheers
 Sheerstrakes
 Topsides
 Wales
 Plank (Bottom) and Counter
 Treenails
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame at the Openings
 Ditto ditto at other places
 Keelsons
 Clamps and Shelves
 Ceiling
 Rudder
 Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways

Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c.
 Condition, how ascertained
 Sails
 Anchors, No. of
 Cables
 Hawesers and Warps
 Standing and Running Rigging

Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches

General Observations, Opinion as to Class, &c.

Committee's Minute

18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18