

27441
Report of Survey for Repairs of Engines and Boilers.

No. 157
Reg. Book. Survey held at *Cardiff, Timor* Date, first Survey *22nd May* Last Survey *8th June* 1880
350 on the Machinery of the *SS. Timor* (Number of Visits *2*)
Tonnage, Gross *2209* Built at *Newcastle* When built *1872*
Ditto, Net *1440* Owners *Nelson Docking & Co* Port belonging to *London*
Diameter of Cylinder *36" x 68"* Engines made by *Maudslayi & Field* When made *1872*
Length of Stroke *45"* Boilers made by *()* When made *1872*
Pressure of Steam *65 lb* ☒ Surveyed Afloat *on in Dry Dock* Years assigned *100* Character in Register Book *A1*
Registered Horse Power *200* Classed *5.79*
Last Survey No. *23619* Port *Rou*

Particulars of Repairs and Examination *on account of condition of*
crankshaft, badly flamed in the second bearing.
A new crankshaft fitted.

General Observations, Opinion, and Recommendation:— *The Machinery is now*
in good condition and safe working order and in
my opinion eligible to remain as classed.

Entry or Registering Fee ... £ : :
Survey Fee ... £ *1* : :
Certificate (if required) ... £ : :
received by me, *ASM*
20th July 1880

Travelling Expenses, if any, £

Committee's Minute

Assigned


ASM
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

S. Timor

His excellency that his
name is eligible to
be named as chosen

M.

3/17/68



© 2019

Lloyd's Register
Foundation